HARMONY Honda

THE HARMONY GUARANTEE - WE GUARANTEE YOU'LL LIKE YOUR PRE-OWNED VEHICLE

1. No Documentation Fees or Hidden Charges
2. 120 Point Inspection on Every Pre-Owned Vehicle
3. 30 Day 2500 KM Exchange Policy
4. Complete Vehicle Detail
5. CarProof Vehicle History Report
6. Full Tank of Gas

2013 FORD ESCAPE

STOCK #: 19580A

VIN NUMBER: 1FMCU9GX5DUC57884

COLOUR: SILVER

ODOMETER: 153,156

SEATS: 5

ENGINE: 1.6L / 4CYL

TRANSMISSION: AUTOMATIC

Front Brake Life: 70 %

Rear Brake Life: 60 %

Front Tire Tread Life: 100 %

Rear Tire Tread Life: 100 %

WHAT MAKES THIS VEHICLE UNIQUE?

- TRADED ON 2019 CR-V!!!
- NOT SMOKED IN!!!
- BC VEHICLE!!!
- NEW TIRES!!!

For more information on this vehicle visit **www.harmonyhonda.com**

PRICE $13,900

2550 Enterprise Way
Kelowna, BC
V1X 7X5
PH: 250-860-6500

Monday - Thursday 8am - 7pm
Friday - Saturday 8am - 6pm
Closed Sunday
www.harmonyhonda.com

HARMONY Honda

USED CAR CHECK-IN SHEET

SALES REP: Greg

YEAR	MAKE	TRIM	ENGINE DISP.	# CYL	ENG HP	MILEAGE	STOCK #
2013	Ford	SE					
	MODEL Escape	BODY SUV	1.6L	4	178	153,156	19580A

VIN	TRANS.	COLOUR - EXT.	COLOUR - INT.
1FMCU9GX5DUC57884	Auto	Silve	Grey

EQUIPMENT

- ___ AM/FM Stereo
- ✓ AM/FM Stereo w/CD
- ___ DVD System (RES)
- ✓ Bluetooth
- ✓ Air Conditioning
- ✓ Cruise Control
- ✓ Tilt Steering
- ___ Leather Interior
- ✓ Power Windows/Mirrors
- ✓ Power Door Locks
- ___ Power Trunk
- ✓ Floor Mats
- ✓ Alloy Wheels
- ✓ Remote Keyless Entry
- ___ Power Driver's Seat
- ___ Dual Power Seats
- ✓ Cooled Seats / ~~Heated Seats~~
- ___ Push Button Start
- ___ Navigation System
- ___ Backup Camera
- ___ Blind Spot Monitors
- ___ Rear Spoiler
- ___ Sunroof / Panoramic Roof
- ___ Fog Lights
- ✓ Tire Pressure Monitoring System (TPMS)
- ✓ Driver's Side Airbags (SIR)
- ✓ Dual Airbags (SIR)
- ✓ Side Airbags
- ___ Side Curtain Airbags
- ___ Anti-Lock Brakes / VSA
- ___ Anti-Theft Device
- ___ Drive Train - 4WD / (AWD) / FWD / RWD / 4X4
- 5 Seats (# of)
- ___ Accessories Door Code - 69132
- ___ Other
- ___ Other

___ Active Safety Radars / Driver Assist Technologies: _____

FACTORY WARRANTY EXPIRES: _____ DATE OR _____ MILEAGE

DECLARATIONS

Any Accidents/Damage	✓ Yes	___ No
Damage Over $2000	✓ Yes	___ No
Ex-Lease	___ Yes	✓ No
Ex-Rental	___ Yes	✓ No
Out of Province	___ Yes	✓ No
If Yes, Province:		

OTHER INFORMATION

Extra Keys	✓ Yes	___ No
Extra Remotes	✓ Yes	___ No
Owner's Manual	✓ Yes	___ No
Radio Code		
Key Code		

VEHICLE HISTORY

What makes this vehicle unique?

(I.E.: Traded in on? # of owners? Purpose of vehicle use? Previous customer info? No accidents? Bought & serviced at Harmony?)

1) Traded on 2019 CRV
2) Non Smoking
3)
4)
5)

SETS OF TIRES

2nd ___ Yes ✓ No

ON RIMS? ___ Yes ✓ No

Front Tires	100	%
Rear Tires	100	%

Front Brakes	70	%
Rear Brakes	60	%

	✓	#
Safety	✓	
Detail	✓	
Online	✓	

Price $ 13,900

QF10c Rev.F
Sep-17

CARFAX CANADA

VERIFIED BC VEHICLE HISTORY REPORT

VEHICLE DETAILS:
VIN: 1FMCU9GX5DUC57884
Year/Make/Model: 2013 FORD ESCAPE SE
Body Style: SPORT UTILITY VEHICLE
Country of Assembly: United States
Cylinders: 4
Fuel Type: Gas

REPORT DETAILS:
Report Number: 25779188
Report Date: 10/4/2019 05:51 PM EST
Report Status: Complete
Reference:

REPORT SUMMARY

Accidents / Damage:	Damage records found
Lien Records:	No lien records found
Canadian Registration:	British Columbia (Normal)
Stolen Status:	Not actively declared stolen
U.S. History:	No U.S. history found
Recalls:	No information available
Service History:	4 record(s) found

QUESTIONS?
WE'RE HERE TO HELP.
CALL
1.866.835.8612
EMAIL
SUPPORT@CARFAX.CA

Report Findings in Chronological Order

Below are all records for the vehicle, listed in the order that they occurred.

Date	Location	Data Source	Type of Record	Detail	Odometer
04/06/2013	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
04/06/2013	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	First Owner Reported	
04/12/2013	Quesnel, British Columbia, Canada	Cariboo Ford Sales	Service Record	Vehicle serviced	
06/29/2013	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
01/14/2014	British Columbia, Canada	Insurance Records	Glass Record	$777.27	
06/14/2014	Quesnel, British Columbia, Canada	Cariboo Ford Sales	Service Record	Vehicle serviced	28,267 KM
06/28/2014	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
09/26/2014	British Columbia, Canada	Insurance Records	Glass Record	$841.47	
10/11/2014	Quesnel, British Columbia, Canada	Cariboo Ford Sales	Service Record	Vehicle serviced	38,367 KM
02/03/2015	Quesnel, British Columbia, Canada	Cariboo Ford Sales	Service Record	Vehicle serviced	45,329 KM
10/03/2015	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
10/03/2015	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	New Owner Reported	
12/24/2015	British Columbia, Canada	Insurance Records	ANIMAL COLLISION	RIGHT FRONT CORNER	
01/23/2017	British Columbia, Canada	Insurance Records	Glass Record	$912.42	
04/10/2017	British Columbia, Canada	Insurance Records		LEFT FRONT CORNER	
06/30/2017	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	

Date	Location	Data Source	Type of Record	Detail	Odometer
09/30/2017	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
10/07/2018	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	

Accident, Collision and Damage Detail

If the vehicle has had any history of accidents, collisions or damage in either Canada or the U.S., the records are outlined in this section. This report also includes claims and estimates from ICBC.

VIN: 1FMCU9GX5DUC57884

Police Reported Accidents

Incident Date	Location	Detail
No police reported accidents found		

Accident/Damage Estimates

Accident estimate records are generated by collision estimating facilities from the process of estimating the amount and extent of damage to a vehicle. Estimates in some cases have associated insurance claims.

Incident Date	Location	Estimate Date	Type of Record	Detail	Amount	Odometer
No estimates found						

Insurance Claims

The insurance claims identified in this report do not include any medical pay-outs, damage to other vehicles, damage to property, towing, rental cars, or any other incidental damages.

Incident Date	Location	Type of Claim	Detail	Amount	Odometer
12/24/2015	British Columbia, Canada	ANIMAL COLLISION	RIGHT FRONT CORNER	$10,719.68	
04/10/2017	British Columbia, Canada		LEFT FRONT CORNER	$1,898.21	

Other Damage Records

Record Date	Location	Type of Record	Detail	Odometer
01/14/2014	British Columbia, Canada	Glass Record	$777.27	
09/26/2014	British Columbia, Canada	Glass Record	$841.47	
01/23/2017	British Columbia, Canada	Glass Record	$912.42	

Lien Status

This section lists the provinces and territories where we searched for or found a security interest registered against the vehicle (lien). If a lien is found, further details will appear at the end of the report.

Province	Lien
British Columbia	No lien found

CARFAX Canada Canadian Lien Guarantee

Our search results accurately reflect the government records of each personal property and security registry in Canada that is searched at the time the search request is made. If for some reason our search report fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian ($5,000.00), whichever is lower.

Canadian Registration

This section details where in Canada the vehicle is now or has ever been registered, as well as the status (Inspection Required, Normal, Non-repairable, Rebuilt, Salvage, Stolen) of the vehicle in those jurisdictions.

Jurisdiction	Branding	Detail
Alberta	Not found	
British Columbia	**NORMAL**	**This vehicle has been registered as Normal in this jurisdiction.**
Manitoba	Not found	
New Brunswick	Not found	
Newfoundland	Not found	
Nova Scotia	Not found	
Northwest Territories	Not found	
Nunavut	Not found	
Ontario	Not found	
Prince Edward Island	Not found	
Quebec	Not found	
Saskatchewan	Not found	
Yukon Territories	Not found	

Stolen Vehicle Check

This section outlines data from the Canadian Police Information Centre (CPIC), which is operated by the RCMP under the stewardship of National Police Services, on behalf of the Canadian law enforcement community.

Stolen Vehicle Check

Not declared stolen.

Import Records

If the vehicle has been imported, you will find the details below.

Import Records

No vehicle import records found

United States Vehicle History

In addition to information about the vehicle's history in Canada, CARFAX Canada also searches for information about the vehicle's history in the United States. If we discover any events in the U.S., you will find them below. Details about accidents, collisions and damage, or any import records will appear in the preceding sections of your report.

U.S. History Records

No U.S. history records found

Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact FORD or visit Ford's website.

Service History

These are records of service performed on the vehicle. These are the records reported to CARFAX Canada when this report was run – it is possible that service has occurred that is not captured here.

Date	Address	Data Source	Type of Record	Detail	Odometer
04/12/2013	Quesnel, British Columbia, Canada	Cariboo Ford Sales	Service Record	Vehicle serviced Accessories installed Remote start installed	

Date	Address	Data Source	Type of Record	Detail	Odometer
06/14/2014	Quesnel, British Columbia, Canada	Cariboo Ford Sales	Service Record	Vehicle serviced Engine/powertrain computer/module reprogrammed Airbag computer/module reprogrammed Computer reprogrammed Intermediate shaft seal replaced	28,267 KM
10/11/2014	Quesnel, British Columbia, Canada	Cariboo Ford Sales	Service Record	Vehicle serviced Front axle(s) replaced/repaired Noise checked	38,367 KM
02/03/2015	Quesnel, British Columbia, Canada	Cariboo Ford Sales	Service Record	Vehicle serviced Transfer case removed to complete repairs	45,329 KM

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts.

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner.
The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim.
In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.
Consumers are encouraged to read ICBC's full statement of limitations at http://apps.icbc.com/registration/vchr/Limitation.html.
ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

CARFAX CANADA © Copyright 2005 - 2019 CARFAX Canada ULC. All rights reserved.

Information on Reports

Conditions of Use

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

Please note CARPROOF recently changed its name to CARFAX Canada!

HARMONY Honda

2550 Enterprise Way, Kelowna BC, V1X-7X5
Phone: 250-860-6530 • Fax: 250-860-6562
Toll Free: 1-877-914-6632 • service@harmonyhonda.com
www.harmonyhonda.com • GST: 10144 7027 RT0001

Promised: 10/04/2019 5:30:00 PM
PO
Fleet
Tag#:

REPRINT

Cashiered Date: 10/08/2019 1:42:17 PM

* Service Invoice Internal Copy *

SO #: 328393

Customer No: 1

HARMONY HONDA HARMONY AUTO SALE
2550 ENTERPRISE WAY
KELOWNA, BC V1X 7X5

Home: (250) 860-6500 **Bus:** (250) 860-6500
Cell: **Today:**(250) 860-6500
Email: reception@harmonyhonda.com

Advisor: Quinn Binkley **Invoice Date:** 10/08/2019 **Term:** CHARGE

License No	Odometer In	Odometer Out	Delivery Date	Stock No
	153156	153158		19580A

Year	Make	Model	Model No	Colour
2013	FORD	ESCAPE	U9G	SILVER

Vehicle ID No	Selling Dealer	SO Date	InServ Date	Location
1FMCU9GX5DUC57884		10/04/2019		

Engine Size 1.6L I4 ECOBOOST ENGINE **Fleet#**

Request/Concern			Type	CSR	Amount
1	SAFETY	USED CAR DEPT			
	SAFETY	USED CAR DEPT	I	51	210.00

QTY	OH					RETAIL	Price	Ext
5	-41	BULK	020HO	0W20 SYTH OIL	I	8.40	8.40	42.00
1	0	SP-OR	NPN	OIL FILTER	I	14.38	14.38	14.38

Name 1093

Cause: INTERNAL SAFETY
Correction: .

Request Total **266.38**

2	DETAIL	COMPLETE DETAIL			
	DETAIL	COMPLETE DETAIL	I	51	0.00

Name 99H

Cause: PRO SMART WED.

Request Total **0.00**

Added Operation

3	411199	TPMS SENSOR /REPLACE RIGHT FRONT & LEFT REAR -PROGRAM			
	411199	TPMS SENSOR /REPLACE RIGHT FRONT & LEFT REAR -PROGRAM	I	922	33.30

QTY	OH					RETAIL	Price	Ext
2	0	SP-OR	NPN	TPMS SENSOR	I	101.83	101.83	203.66

Name 1093

Cause: DIAGNOSED AND REPLACED 2 TPMS SENSORS.
Correction: .

Request Total **236.96**

Added Operation

4	BLADES	WIPER BLADES /FRONT			
	BLADES	WIPER BLADES /FRONT	I	922	0.00

I understand that Honda, its affiliates, dealers and service providers collect, use and disclose my personal information for the purposes of (i) completing my purchase, finance or lease transaction; (ii) maintaining my warranty and customer service records; (iii) conducting customer service campaigns; (iv) providing me with marketing information; and (v) for legal and other business purposes. I consent to Honda, its affiliates, dealers and service providers contacting me by telephone or sending commercial electronic messages to me, including email and text messages. I can contact Honda at 1-888-946-6329 or 180 Honda Boulevard, Markham, Ontario, L6C 0H9, and my dealer if I no longer consent of these uses and to update or correct my personal information.

X _____
CUSTOMER SIGNATURE

PARTS AND SERVICE HOURS
MONDAY-FRIDAY
7:30AM-5:30PM
SATURDAY
8:00AM–4:00PM

Book your service at harmonyhonda.com and trust your ride to us.

Thank you - Jeff Hautamaki
Fixed Operations Manager

HARMONY Honda

2550 Enterprise Way, Kelowna BC, V1X-7X5
Phone: 250-860-6530 • Fax: 250-860-6562
Toll Free: 1-877-914-6632 • service@harmonyhonda.com
www.harmonyhonda.com • GST: 10144 7027 RT0001

Promised: 10/04/2019 5:30:00 PM
PO
Fleet
Tag#:

REPRINT

Cashiered Date: 10/08/2019 1:42:17 PM

* Service Invoice Internal Copy *

SO #: 328393

Customer No: 1

HARMONY HONDA HARMONY AUTO SALE
2550 ENTERPRISE WAY
KELOWNA, BC V1X 7X5

Home: (250) 860-6500 **Bus:** (250) 860-6500
Cell: **Today:**(250) 860-6500
Email: reception@harmonyhonda.com

Advisor: Quinn Binkley **Invoice Date:** 10/08/2019 **Term:** CHARGE

License No	Odometer In	Odometer Out	Delivery Date	Stock No
	153156	153158		19580A

Year	Make	Model	Model No	Colour
2013	FORD	ESCAPE	U9G	SILVER

Vehicle ID No	Selling Dealer	SO Date	InServ Date	Location
1FMCU9GX5DUC57884		10/04/2019		

Engine Size 1.6L I4 ECOBOOST ENGINE **Fleet#**

Request/Concern — **Type** — **CSR** — **Amount**

QTY	OH					RETAIL	Price	Ext
2	0	SP-OR	NPN	BLADES	I	34.43	34.43	68.86

Name 1093

Cause: .
Correction: .

Request Total 68.86

Added Operation

5	ROTORS	REPLACE FRONT BRAKE ROTORS	
	ROTORS	REPLACE FRONT BRAKE ROTORS	I 922 168.00

QTY	OH					RETAIL	Price	Ext
2	0	SP-OR	NPN	FR/BRAKE ROTORS	I	115.45	115.45	230.90
1	91	FLUID	CA66932	CONT/BRKE CLEANER	I	8.21	8.21	8.21

Name 1093

Cause: .
Correction: .

Request Total 407.11

Added Operation

6	03HOZZ52111	MOUNT AND BALANCE 4 NEW TIRES ON VEHICLE WITH TIRE 235/55/17 BFGs 29257	
	03HOZZ52111	MOUNT AND BALANCE 4 NEW TIRES ON VEHICLE WITH TIRE 235/55/17 BFGs 29257	I 922 116.00

QTY	OH					RETAIL	Price	Ext
4	0	SP-OR	29257	235/55R17 BFG	I	207.82	207.82	831.28
4	0	SP-OR	TT	TIRE TAX	I	5.00	5.00	20.00

Name 1093

Cause: .
Correction: .

Request Total 967.28

I understand that Honda, its affiliates, dealers and service providers collect, use and disclose my personal information for the purposes of (i) completing my purchase, finance or lease transaction; (ii) maintaining my warranty and customer service records; (iii) conducting customer service campaigns; (iv) providing me with marketing information; and (v) for legal and other business purposes. I consent to Honda, its affiliates, dealers and service providers contacting me by telephone or sending commercial electronic messages to me, including email and text messages. I can contact Honda at 1-888-946-6329 or 180 Honda Boulevard, Markham, Ontario, L6C 0H9, and my dealer if I no longer consent of these uses and to update or correct my personal information.

X _____
CUSTOMER SIGNATURE

PARTS AND SERVICE HOURS
MONDAY-FRIDAY
7:30AM-5:30PM
SATURDAY
8:00AM–4:00PM

Book your service at harmonyhonda.com and trust your ride to us.

Thank you - Jeff Hautamaki
Fixed Operations Manager

HARMONY Honda

2550 Enterprise Way, Kelowna BC, V1X-7X5
Phone: 250-860-6530 • Fax: 250-860-6562
Toll Free: 1-877-914-6632 • service@harmonyhonda.com
www.harmonyhonda.com • GST: 10144 7027 RT0001

Promised: 10/04/2019 5:30:00 PM
PO
Fleet
Tag#:

REPRINT

Cashiered Date: 10/08/2019 1:42:17 PM

* Service Invoice Internal Copy *

SO #: 328393

Customer No: 1

HARMONY HONDA HARMONY AUTO SALE
2550 ENTERPRISE WAY
KELOWNA, BC V1X 7X5

Home: (250) 860-6500 **Bus:** (250) 860-6500
Cell: **Today:**(250) 860-6500
Email: reception@harmonyhonda.com

Advisor: Quinn Binkley **Invoice Date:** 10/08/2019 **Term:** CHARGE

License No	Odometer In	Odometer Out	Delivery Date	Stock No
	153156	153158		19580A

Year	Make	Model	Model No	Colour
2013	FORD	ESCAPE	U9G	SILVER

Vehicle ID No	Selling Dealer	SO Date	InServ Date	Location
1FMCU9GX5DUC57884		10/04/2019		

Engine Size 1.6L I4 ECOBOOST ENGINE **Fleet#**

Request/Concern			Type	CSR	Amount
Added	**Operation**				
7	MPI-HONDA	Honda Canada Multi-Point Vehicle Inspection Checklist			
	HI	COMPLIMENTARY HONDA VEHICLE MULTI-POINT INSPECTION	I	51	0.00

Name 1093

Cause: MULTI POINT INSPECTION

Correction: PERFORMED HONDA FACTORY MULTI-POINT INSPECTION, DETAILS INCLUDED ON PRINT OUT

Request Total **0.00**

	LABOUR SALE	PARTS SALE	OIL/GAS	MISC.	SUPPLIES	SUBLET /TOW	ENV FEE	WARR DEDUCTIBLE	GST	PST	TOTAL
C	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
W	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
I	527.30	1,419.29	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	1,946.59
TOTALS	527.30	1,419.29	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	1,946.59

INTERNAL DETAILS

Account	Description	Type	Control #	Amount	Comments
138	USED VEHICLE INVENTORY	U	19580A	1,946.59	19580A - 2013 FORD ESCAPE SE

I understand that Honda, its affiliates, dealers and service providers collect, use and disclose my personal information for the purposes of (i) completing my purchase, finance or lease transaction; (ii) maintaining my warranty and customer service records; (iii) conducting customer service campaigns; (iv) providing me with marketing information; and (v) for legal and other business purposes. I consent to Honda, its affiliates, dealers and service providers contacting me by telephone or sending commercial electronic messages to me, including email and text messages. I can contact Honda at 1-888-946-6329 or 180 Honda Boulevard, Markham, Ontario, L6C 0H9, and my dealer if I no longer consent of these uses and to update or correct my personal information.

X _____
CUSTOMER SIGNATURE

PARTS AND SERVICE HOURS
MONDAY-FRIDAY
7:30AM-5:30PM
SATURDAY
8:00AM–4:00PM

Book your service at harmonyhonda.com and trust your ride to us.

Thank you - Jeff Hautamaki
Fixed Operations Manager

Honda Multi-Point Vehicle Inspection Checklist

HONDA GENUINE PARTS & SERVICE

BOOK YOUR NEXT SERVICE APPOINTMENT ONLINE.

R/O Number: 328393

Customer Name: HARMONY HONDA

Odometer: ~~153156~~ HARMONY AUTO SALES LTD

Next Service Due: A [X] B [ ]

Advisor: Quinn Binkley

Technician: Karlin Gamache

Satisfactory | May Require Further Attention | Requires Immediate Attention

Interior/Exterior				
Headlights (check high and low beams)	X			
Taillights	X			
Turn signals	X			
Brake lights	X			
Hazard warning lights	X			
Interior light	X			
Windshield washer spray, wiper operation and wiper blades	X			
Windshield condition	X			
Parking brake	X			
Horn operation	X			
Clutch operation (if applicable)				

Battery Performance (see printout)		Date of Manufacture
Good	X	
Replace		

Under Hood			
Engine oil level	X		
Coolant level	X		
Power steering fluid level	X		
Brake fluid level	X		
Windshield washer fluid level	X		
Transmission fluid level	X		
External drive belts and radiator hoses	X		
Air/Cabin/Dust & Pollen Filter	X		
Under Vehicle			
Brake lines/Hoses/Parking brake cable	X		
Hydraulic clutch reservoir fluid (M/T vehicles)			
Shock absorbers/Struts/Suspension	X		
Exhaust system	X		
Engine oil and/or fluid leaks	X		
Drive shaft/Constant velocity boots and bands	X		
Steering Gearbox Components	X		

Genuine Floor Mats		
Genuine floor mats installed	X	
Anchored properly and only 1 mat at driver's position	X	

*NOTE: Brake fluid NOT filled - fluid level indicates pad wear

Tire Condition — 6/32 or more | 4/32 to 5/32 | 3/32 or less

Left Front		Right Front
Wear pattern		Wear pattern
Tire tread 100 32nds		Tire tread 100 32nds
Left Rear		**Right Rear**
Wear pattern		Wear pattern
Tire tread 100 32nds		Tire tread 100 32nds
Spare		
Wear pattern	Front tire inflation set to 33 psi	
Tire tread _____ 32nds	Rear tire inflation set to 33 psi	
Rotation/Alignment/Replacement suggested?	Yes [ ]	No [X]
Seasonal tire changeover suggested?	Yes [ ]	No [X]

Brake Inspection Not Performed At This Service [ ]

Brake Condition — 5 mm or more | 3 - 4 mm | 2 mm or less

Left Front		Right Front
_____ mm 70 %		_____ mm 70 %
Left Rear		**Right Rear**
_____ mm 60 %		_____ mm 60 %

Please Indicate Areas of External Damage or Wear



Maintenance Indicator Light Reset YES [X]

Any Outstanding Recalls / PUD YES [ ] NO [ ]

Comments

Lowest Price Guarantee on Tires* | Lifetime Brake Pad Guarantee* | Lowest Price Guarantee on 0W-20 Oil Changes*