HARMONY ACURA

THE HARMONY GUARANTEE - WE GUARANTEE YOU'LL LIKE YOUR PRE-OWNED VEHICLE

1. No Documentation Fees or Hidden Charges
2. 120 Point Inspection on Every Pre-Owned Vehicle
3. 30 Day 2500 KM Exchange Policy
4. Complete Vehicle Detail
5. CarProof Vehicle History Report
6. Full Tank of Gas

2010 NISSAN ALTIMA SR

STOCK #: A22059A

VIN NUMBER: 1N4BL2EP2AC172926

COLOUR: RED

ODOMETER: 162,428

SEATS: 5

ENGINE: 3.5L/6CYL

TRANSMISSION: MANUAL

Front Brake Life: 70 %

Rear Brake Life: 70 %

Front Tire Tread Life: 60 %

Rear Tire Tread Life: 60 %

WHAT MAKES THIS VEHICLE UNIQUE?

- ONE OWNER!!!
- WELL SERVICED!!!
- NO ACCIDENTS!!!
- 6 SPEED MANUAL!!!
- SPORTY!!!

For more information on this vehicle visit www.harmonyacura.com

PRICE $15,900

2552 Enterprise Way
Kelowna, BC
V1X 7X5
PH: 250-861-3003

Monday - Friday 8am - 7pm
Saturday 9am - 6pm
Closed Sunday

www.harmonyacura.com

HARMONY ACURA

USED CAR CHECK-IN SHEET

SALES REP: Sachin

YEAR	MAKE	TRIM	ENGINE DISP.	# CYL	ENG HP	MILEAGE	STOCK #
2010	Nissan	SR	3.5L	6	270HP	162,428	A22059A
	MODEL Altima	BODY Coupe					

VIN	TRANS.	COLOUR - EXT.	COLOUR - INT.
1N4BL2EP2AC172926	6spd. Manual	Red	Black

EQUIPMENT

- ___ AM/FM Stereo
- ✓ AM/FM Stereo w/CD
- ___ DVD System (RES)
- ✓ Bluetooth
- ✓ Air Conditioning
- ✓ Cruise Control
- ✓ Tilt Steering
- ✓ Leather Interior
- ✓ Power Windows/Mirrors
- ✓ Power Door Locks
- ✓ Power Trunk
- ___ Floor Mats
- ✓ Alloy Wheels
- ✓ Remote Keyless Entry
- ✓ Power Driver's Seat
- ___ Dual Power Seats
- ✓ Cooled Seats / Heated Seats
- ✓ Push Button Start
- ___ Navigation System
- ___ Backup Camera
- ___ Blind Spot Monitors
- ___ Rear Spoiler
- ✓ Sunroof / Panoramic Roof
- ✓ Fog Lights
- ✓ Tire Pressure Monitoring System (TPMS)
- ✓ Driver's Side Airbags (SIR)
- ✓ Dual Airbags (SIR)
- ___ Side Airbags
- ___ Side Curtain Airbags
- ✓ Anti-Lock Brakes / VSA
- ✓ Anti-Theft Device
- ✓ Drive Train - 4WD / AWD / FWD / RWD / 4X4
- ✓ Seats (# of) 5
- ___ Accessories
- ___ Other
- ___ Other

___ Active Safety Radars / Driver Assist Technologies:

FACTORY WARRANTY EXPIRES: _____ DATE OR _____ MILEAGE

DECLARATIONS

Any Accidents/Damage	___ Yes	✓ No
Damage Over $2000	___ Yes	✓ No
Ex-Lease	___ Yes	✓ No
Ex-Rental	___ Yes	✓ No
Out of Province	___ Yes	✓ No
If Yes, Province:		

OTHER INFORMATION

Extra Keys	✓ Yes	___ No
Extra Remotes	✓ Yes	___ No
Owner's Manual	✓ Yes	___ No
Radio Code		
Key Code		

VEHICLE HISTORY

What makes this vehicle unique?

(I.E.: Traded in on? # of owners? Purpose of vehicle use? Previous customer info? No accidents? Bought & serviced at Harmony?)

1) One Owner
2) B.C. Vehicle
3) No Accidents
4) 6 speed Manual
5) Sporty!

Well Serviced!

SETS OF TIRES

2nd ___ Yes ✓ No

ON RIMS? ___ Yes ✓ No

Front Tires	60	%	Front Brakes	70	%
Rear Tires	60	%	Rear Brakes	70	%

	✓	#
Safety	✓	
Detail	✓	
Online	✓	

Price $ 15,900

QF10d Rev.C
Sep-17

Vehicle History Report + Lien Check (BC) #: 38098660
Report Date: March 1, 2022 | 04:50 PM EST
Report Status: Complete
Reference:

2010 NISSAN ALTIMA SR

Coupe | 6 Cylinders | Gas
1N4BL2EP2AC172926
Country of Assembly: United States
Last Reported Odometer: 160,807 KM

ONE OWNER* NO REPORTED ACCIDENTS*

LIEN CHECK

No Lien Records Found

Glass Records found

Last Registered In:
British Columbia (Normal)

8 Service Records Found

No U.S. History Found

No Open Recalls Found

Not Actively Declared Stolen

No Import Record Found

Questions? We're here to help.
Visit us at **support.carfax.ca**

This vehicle history report is based on information that was reported and available to CARFAX Canada as of March 01, 2022 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

1N4BL2EP2AC172926

Vehicle History Report + Lien Check (BC)

Lien Check

No lien records found in **British Columbia.**

How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

CARFAX Canada Canadian Lien Guarantee

If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian ($5,000.00), whichever is lower.

Accident/Damage

There are no police reported accidents, estimates, or claims reported on this vehicle, however, we found other damage records that are outlined below.

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2010 Sep 30	**British Columbia, Canada**	
	Glass Record	$668.23

Registration

This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*

Service Records

DATE	ODOMETER	SOURCE	DETAILS

1N4BL2EP2AC172926

DATE	ODOMETER	SOURCE	DETAILS
2010 Jul 12		Kelowna Nissan/Kelowna Mercedes-Benz Kelowna, British Columbia, Canada	**Vehicle serviced** • Pre-delivery inspection completed • Nitrogen fill tires
2011 May 13		Kelowna Nissan/Kelowna Mercedes-Benz Kelowna, British Columbia, Canada	**Vehicle serviced** • Vehicle washed/detailed • Door glass replaced
2012 Apr 30		Kelowna Nissan/Kelowna Mercedes-Benz Kelowna, British Columbia, Canada	**Vehicle serviced** • Vehicle washed/detailed • Brakes checked
2012 May 28		Kelowna Nissan/Kelowna Mercedes-Benz Kelowna, British Columbia, Canada	**Vehicle serviced** • Heated seat repaired
2014 May 29	73,185 KM	Sun Valley Nissan Cranbrook, British Columbia, Canada	**Vehicle serviced**
2015 Mar 31	81,768 KM	Sun Valley Nissan Cranbrook, British Columbia, Canada	**Vehicle serviced** • Maintenance inspection completed
2017 Sep 22		Kal Tire 061 Kelowna, British Columbia, Canada	**Vehicle serviced** • One tire mounted • One tire balanced
2022 Jan 13	160,807 KM	Reach Tire and Auto Kelowna, British Columbia, Canada	**Vehicle serviced** • Maintenance inspection completed • Alternator checked • Battery/charging system checked

Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact NISSAN or visit **Nissan's website**.

Stolen Vehicle Check

This vehicle is not actively declared stolen.

Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2010 Jul 12		Kelowna Nissan/Kelowna Mercedes-Benz Kelowna, British Columbia, Canada	Service Record	Vehicle serviced

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2010 Jul 17		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2010 Aug 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2010 Sep 30		Insurance Records British Columbia, Canada	Glass Record	$668.23
2011 May 13		Kelowna Nissan/Kelowna Mercedes-Benz Kelowna, British Columbia, Canada	Service Record	Vehicle serviced
2011 Jul 16		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Apr 30		Kelowna Nissan/Kelowna Mercedes-Benz Kelowna, British Columbia, Canada	Service Record	Vehicle serviced
2012 May 28		Kelowna Nissan/Kelowna Mercedes-Benz Kelowna, British Columbia, Canada	Service Record	Vehicle serviced
2012 Jul 14		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Jul 20		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 May 29	73,185 KM	Sun Valley Nissan Cranbrook, British Columbia, Canada	Service Record	Vehicle serviced
2014 Aug 9		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Mar 31	81,768 KM	Sun Valley Nissan Cranbrook, British Columbia, Canada	Service Record	Vehicle serviced
2015 Aug 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 May 21		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Jul 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Aug 5		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Sep 22		Kal Tire 061 Kelowna, British Columbia, Canada	Service Record	Vehicle serviced
2017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Jul 29		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Jul 14		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Aug 6		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Jul 25		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2022 Jan 13	160,807 KM	Reach Tire and Auto Kelowna, British Columbia, Canada	Service Record	Vehicle serviced

Questions? We're here to help.

Visit us at **support.carfax.ca**

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at http://apps.icbc.com/registration/vchr/Limitation.html.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

CARFAX Canada One Owner™ Badge

The CARFAX Canada One Owner™ badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI.

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. **Conditions of Use**

© Copyright 2005 - 2022 CARFAX Canada ULC. All rights reserved.

CARFAX

1N4BL2EP2AC172926

CUSTOMER #: N/A

209937

INTERNAL

HARMONY ACURA

HARMONY ACURA
2552 ENTERPISE WAY
KELOWNA, BC V1X 7X5

PAGE 1

2552 Enterprise Way Kelowna, BC V1X 7X5
Service Direct: (250) 448-7098
Email: service@harmonyacura.com
GST: 104078324RT0001

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 930 930 930

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
RED	10	NISSAN Altima	1N4BL2EP2AC172926		162428/162428	A22059

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			19:00 10MAR22		0.00	CASH	10MAR22

R.O. OPENED	READY	OPTIONS:
17:49 06MAR22	16:51 10MAR22	STK:A22059A DLR:2021 ENG:3.5_Liter

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
A PERFORM USED CAR SAFETY INSPECTION			
SAFETY PERFORM USED CAR SAFETY INSPECTION			
1093 IUV 1.50		260.00	260.00
GAS FUEL CHARGE		97.85	97.85
1 15208-654F0E FILTER	16.16	16.16	16.16
5 CA670-07 ACURA 5W30 SYNTH	12.08	12.08	60.40
PARTS: 76.56 LABOR: 260.00 OTHER: 97.85 TOTAL LINE A:			434.41
162428 1.50 97.85			
**********			
D** REPLACE TPMS SENSORS			
GEN GENERAL REPAIR			
1093 IUV 1.20		210.00	210.00
4 40700-JK01B SENSORS	84.16	84.16	336.64
PARTS: 336.64 LABOR: 210.00 OTHER: 0.00 TOTAL LINE D:			546.64
162428 1.20			
**********			
E** REPLACE RIGHT INNER TIE ROD			
GEN GENERAL REPAIR			
1093 IUV 1.40		245.00	245.00
1 M3010-1914670 TIE ROD END	17.25	17.25	17.25
PARTS: 17.25 LABOR: 245.00 OTHER: 0.00 TOTAL LINE E:			262.25
162428 1.40			
**********			
F** 4 WHEEL ALIGNMENT $149.95			
ALIGN 4 WHEEL ALIGNMENT $149.95			
1093 IUV 0.80		149.95	149.95
PARTS: 0.00 LABOR: 149.95 OTHER: 0.00 TOTAL LINE F:			149.95
162428 0.80			
**********			
G** REPLACE FRONT ROTORS			
GEN GENERAL REPAIR			
1093 IUV 1.20		210.00	210.00
1 CA66932 CONT/BRKE CLEANER	5.22	5.00	5.00
1 HW2 CLIPS	7.00	7.00	7.00

☐ I Consent to receive commercial electronic messages including news, special offers, advertisements and other promotional information from **HARMONY ACURA**, including its Agents. I can unsubscribe or withdraw my consent at any time using the unsubscribe method provided in the communication, or by contacting **HARMONY ACURA** at **2552 Enterprise Way, Kelowna, BritishColumbia,V1X 7X5, Service@harmonyacura.com** or **Tel# 250-448-7098.**

x_____
CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
TAX	
PLEASE PAY THIS AMOUNT	

PARTS & SERVICE HOURS: MONDAY - FRIDAY 7:30 AM - 5:30 PM SATURDAY 8:00 AM - 4:00 PM

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2CE - IMAGING

INTERNAL COPY

CUSTOMER #: N/A

209937

INTERNAL

HARMONY ACURA

HARMONY ACURA
2552 ENTERPISE WAY
KELOWNA, BC V1X 7X5

2552 Enterprise Way Kelowna, BC V1X 7X5
Service Direct: (250) 448-7098
Email: service@harmonyacura.com
GST: 104078324RT0001

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 930 930 930

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
RED	10	NISSAN Altima	1N4BL2EP2AC172926		162428/162428	A22059

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			19:00 10MAR22		0.00	CASH	10MAR22

R.O. OPENED	READY	OPTIONS:
17:49 06MAR22	16:51 10MAR22	STK:A22059A DLR:2021 ENG:3.5_Liter

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
4	40780-JA01B		NUT		7.92	7.92	31.68
2	40206-JA00A		ROTORS		143.56	143.56	287.12

PARTS: 330.80 LABOR: 210.00 OTHER: 0.00 TOTAL LINE G: 540.80
162428 1.20

****

H** REPLACE REAR ROTORS
GEN GENERAL REPAIR

	1093	IUV	1.20			210.00	210.00
1	CA66932	CONT/BRKE CLEANER			5.22	5.00	5.00
1	HW2	CLIPS			7.00	7.00	7.00
2	43206-JA00A	ROTORS			414.59	414.59	829.18

PARTS: 841.18 LABOR: 210.00 OTHER: 0.00 TOTAL LINE H: 1051.18
162428 1.20

****

I** REPLACE FRONT SWAY BAR LINKS
GEN GENERAL REPAIR

	1093	IUV	1.00			175.00	175.00
1	54618-JA000	SWAY BAR LINK			93.72	93.72	93.72
1	54668-JA000	SWAY BAR LINK			84.63	84.63	84.63

PARTS: 178.35 LABOR: 175.00 OTHER: 0.00 TOTAL LINE I: 353.35
162428 1.00

****

J** REPLACE REAR COIL SPRINGS
GEN GENERAL REPAIR

	1093	IUV	2.00			350.00	350.00
2	55020-JB01D	SPRINGS			134.14	134.14	268.28

PARTS: 268.28 LABOR: 350.00 OTHER: 0.00 TOTAL LINE J: 618.28
162428 2.00

****

K** REPLACE WIPER BLADES- 2
WIPER REPLACE WIPER BLADES

	1093	IUV	0.00			0.00	0.00
1	B889U-HS171J	BLADE			21.95	21.95	21.95
1	B889U-HS26J	BLADE			21.95	21.95	21.95

☐ I Consent to receive commercial electronic messages including news, special offers, advertisements and other promotional information from **HARMONY ACURA**, including its Agents. I can unsubscribe or withdraw my consent at any time using the unsubscribe method provided in the communication, or by contacting **HARMONY ACURA** at **2552 Enterprise Way, Kelowna, BritishColumbia,V1X 7X5, Service@harmonyacura.com** or **Tel# 250-448-7098.**

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
TAX	
PLEASE PAY THIS AMOUNT	

x_____
CUSTOMER SIGNATURE

PARTS & SERVICE HOURS: MONDAY - FRIDAY 7:30 AM - 5:30 PM SATURDAY 8:00 AM - 4:00 PM

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2CE - IMAGING

INTERNAL COPY

CUSTOMER #: N/A

209937

INTERNAL

HARMONY ACURA

HARMONY ACURA
2552 ENTERPISE WAY
KELOWNA, BC V1X 7X5

PAGE 3

2552 Enterprise Way Kelowna, BC V1X 7X5
Service Direct: (250) 448-7098
Email: service@harmonyacura.com
GST: 104078324RT0001

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 930 930 930

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
RED	10	NISSAN Altima	1N4BL2EP2AC172926		162428/162428	A22059

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			19:00 10MAR22		0.00	CASH	10MAR22

R.O. OPENED	READY	OPTIONS:
17:49 06MAR22	16:51 10MAR22	STK:A22059A DLR:2021 ENG:3.5_Liter

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
PARTS: 43.90 LABOR: 0.00 OTHER: 0.00 TOTAL LINE K:			43.90
**********			
L** ADJUST E BRAKE			
GEN GENERAL REPAIR			
1093 IUV 0.50		87.50	87.50
PARTS: 0.00 LABOR: 87.50 OTHER: 0.00 TOTAL LINE L:			87.50
162428 0.50			
**********			
M** INSTALL LATCH ASSEMBLY			
GEN GENERAL REPAIR			
1093 IUV 0.60		105.00	105.00
1 84630-9N00A TRUNK LATCH	90.00	90.00	90.00
PARTS: 90.00 LABOR: 105.00 OTHER: 0.00 TOTAL LINE M:			195.00
162428 0.60			
**********			

EST: 734.95 10MAR22 08:31 SA: 930
CONTACT: W
****

COST/SALE/COMP TOT: 171405 428326 0

☐ I Consent to receive commercial electronic messages including news, special offers, advertisements and other promotional information from **HARMONY ACURA**, including its Agents. I can unsubscribe or withdraw my consent at any time using the unsubscribe method provided in the communication, or by contacting **HARMONY ACURA** at **2552 Enterprise Way, Kelowna, BritishColumbia,V1X 7X5, Service@harmonyacura.com** or **Tel# 250-448-7098.**

x_____
CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOUR AMOUNT	2002.45
PARTS AMOUNT	2182.96
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	97.85
TOTAL CHARGES	4283.26
LESS INSURANCE	0.00
TAX	0.00
PLEASE PAY THIS AMOUNT	4283.26

PARTS & SERVICE HOURS: MONDAY - FRIDAY 7:30 AM - 5:30 PM SATURDAY 8:00 AM - 4:00 PM

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2CE - IMAGING

INTERNAL COPY

Acura Multi-Point Vehicle Inspection Checklist

ACURA TIRE SOURCE

ACURA ADVANCE.

HARMONY ACURA

R/O NUMBER 209937	NEXT SERVICE DUE
CUSTOMER NAME VEHICLE INVENTORY	ODOMETER 162428
SERVICE ADVISOR Julie Schaufert	TECHNICIAN Karlin Gamache

Satisfactory | May Require Further Attention | Requires Immediate Attention

Interior/Exterior	✓		
Headlights (check high and low beams)	✓		
Taillights	✓		
Turn signals	✓		
Brake lights	✓		
Hazard warning lights	✓		
Interior light	✓		
Windshield washer spray, wiper operation and wiper blades	✓		
Windshield condition	✓		
Parking brake	✓		
Horn operation	✓		
Clutch operation (if applicable)			

Battery Performance (see printout)		
Good	✓	
Replace		mm/dd/yyyy

Under Hood	✓		
Engine oil level	✓		
Coolant level	✓		
Power steering fluid level	✓		
Brake fluid level	✓		
Windshield washer fluid level	✓		
Transmission fluid level	✓		
External drive belts and radiator hoses	✓		
Air/Cabin/Dust & Pollen Filter	✓		
Under Vehicle			
Brake lines/Hoses/Parking brake cable	✓		
Hydraulic clutch reservoir fluid (M/T vehicles)			
Shock absorbers/Struts/Suspension	✓		
Exhaust system	✓		
Engine oil and/or fluid leaks	✓		
Drive shaft/Constant velocity boots and bands	✓		
Steering Gearbox Components	✓		

Genuine Floor Mats	✓	
Genuine floor mats installed	✓	
Anchored properly and only 1 mat at driver's position	✓	

PAM2269E

**NOTE: Brake fluid NOT filled - fluid level indicates pad wear*

Tire Condition — 6/32 or more | 4/32 to 5/32 | 3/32 or less

Left Front		Right Front
Wear pattern	Wear pattern	
Tire tread 60 32nds	Tire tread 60 32nds	
Left Rear		**Right Rear**
Wear pattern	Wear pattern	
Tire tread 60 32nds	Tire tread 60 32nds	
Spare		
Wear pattern	Front tire inflation set to 35 psi	
Tire tread ____ 32nds	Rear tire inflation set to No psi	

Rotation/Alignment/Replacement suggested? Yes ☐ No ☑

Seasonal tire changeover suggested? Yes ☐ No ☑

Brake Inspection Not Performed At This Service ☐

Brake Condition — 5 mm or more | 3 - 4 mm | 2 mm or less

Left Front		Right Front
____ mm 70 %	____ mm 70 %	
Left Rear		**Right Rear**
____ mm 70 %	____ mm 70 %	

Please Indicate Areas of External Damage or Wear



Maintenance Indicator Light Reset YES ☑ N/A ☐

Any Outstanding Recalls / PUD YES ☐ NO ☑

Comments