HARMONY Honda

THE HARMONY GUARANTEE - WE GUARANTEE YOU'LL LIKE YOUR PRE-OWNED VEHICLE

1. No Documentation Fees or Hidden Charges
2. 120 Point Inspection on Every Pre-Owned Vehicle
3. 30 Day 2500 KM Exchange Policy
4. Complete Vehicle Detail
5. CarProof Vehicle History Report
6. Full Tank of Gas

2010 ACURA MDX

STOCK #: U6869

VIN NUMBER: 2HNYD2H69AH003868

COLOUR: BLACK

ODOMETER: 163,539

SEATS: 7

ENGINE: 3.7L/6CYL

TRANSMISSION: AUTO

Front Brake Life: 75 %

Rear Brake Life: 75 %

Front Tire Tread Life: 100 %

Rear Tire Tread Life: 100 %

WHAT MAKES THIS VEHICLE UNIQUE?

- REAR ENTERTAINMENT SYSTEM !!
- TOW HITCH !!
- WELL SERVICED !!
- ALL WHEEL DRIVE !!

For more information on this vehicle visit www.harmonyhonda.com

PRICE $19,990

2550 Enterprise Way
Kelowna, BC
V1X 7X5
PH: 250-860-6500

Monday - Thursday 8am - 7pm
Friday - Saturday 8am - 6pm
Closed Sunday
www.harmonyhonda.com

HARMONY Honda

USED CAR CHECK-IN SHEET

SALES REP: Andrew

YEAR	MAKE	TRIM	ENGINE DISP.	# CYL	ENG HP	MILEAGE	STOCK #
2010	Acura	Tech	3.7	6	300	163 539	U6869
	MODEL MDX	BODY 5DR					

VIN	TRANS.	COLOUR - EXT.	COLOUR - INT.
2HNYD2H69AH003868	Auto	Black	Beige

EQUIPMENT

- ___ AM/FM Stereo
- ✓ AM/FM Stereo w/CD
- ✓ DVD System (RES)
- ✓ Bluetooth
- ✓ Air Conditioning
- ✓ Cruise Control
- ✓ Tilt Steering
- ✓ Leather Interior
- ✓ Power Windows/Mirrors
- ✓ Power Door Locks
- ✓ Power Trunk
- ✓ Floor Mats
- ✓ Alloy Wheels
- ✓ Remote Keyless Entry
- ✓ Power Driver's Seat
- ✓ Dual Power Seats
- ✓ ~~Cooled Seats~~ / Heated Seats
- ___ Push Button Start
- ✓ Navigation System
- ✓ Backup Camera
- ___ Blind Spot Monitors
- ___ Rear Spoiler
- ✓ Sunroof / Panoramic Roof
- ✓ Fog Lights
- ✓ Tire Pressure Monitoring System (TPMS)
- ✓ Driver's Side Airbags (SIR)
- ✓ Dual Airbags (SIR)
- ✓ Side Airbags
- ✓ Side Curtain Airbags
- ✓ Anti-Lock Brakes / VSA
- ✓ Anti-Theft Device
- ✓ Drive Train - ~~4WD~~ / AWD / ~~FWD / RWD / 4X4~~
- ✓ Seats (# of) 7
- ✓ Accessories 3m, Tow hitch
- ___ Other
- ___ Other

___ Active Safety Radars / Driver Assist Technologies: _____

FACTORY WARRANTY EXPIRES: _____ DATE OR _____ MILEAGE

DECLARATIONS

Any Accidents/Damage	✓ Yes	___ No
Damage Over $2000	✓ Yes	___ No
Ex-Lease	___ Yes	✓ No
Ex-Rental	___ Yes	✓ No
Out of Province	✓ Yes	___ No
If Yes, Province:	AB	

OTHER INFORMATION

Extra Keys	___ Yes	✓ No
Extra Remotes	___ Yes	✓ No
Owner's Manual	✓ Yes	___ No
Radio Code		
Key Code		

VEHICLE HISTORY

What makes this vehicle unique?

(I.E.: Traded in on? # of owners? Purpose of vehicle use? Previous customer info? No accidents? Bought & serviced at Harmony?)

1) Rear entertainment system
2) Low mileage
3) Tow hitch
4) 3M rockguard
5) Well serviced

SETS OF TIRES

2nd ___ Yes ✓ No

ON RIMS? ___ Yes ✓ No

Front Tires	100 %
Rear Tires	100 %

Front Brakes	75 %
Rear Brakes	75 %

Price $ 19,990

	✓	#
Safety	✓	351990
Detail	✓	351990
Online	✓	

QF10c Rev.F
Sep-17

CARFAX CANADA

VERIFIED BC VEHICLE HISTORY REPORT

VEHICLE DETAILS:
VIN: 2HNYD2H69AH003868
Year/Make/Model: 2010 ACURA MDX TECHNOLOGY
Body Style: SPORT UTILITY VEHICLE
Country of Assembly: Canada
Cylinders: 6
Fuel Type: Gas

REPORT DETAILS:
Report Number: 27758626
Report Date: 3/12/2020 04:14 PM EST
Report Status: Complete
Reference:

REPORT SUMMARY

Highlights: ONE OWNER™

Accidents / Damage:	Damage records found
Lien Records:	No lien records found
Canadian Registration:	Alberta (Normal)
Stolen Status:	Not actively declared stolen
U.S. History:	No U.S. history found
Recalls:	No information available
Service History:	7 record(s) found

QUESTIONS?

WE'RE HERE TO HELP.

CALL
1.866.835.8612

EMAIL
SUPPORT@CARFAX.CA

Report Findings in Chronological Order

Below are all records for the vehicle, listed in the order that they occurred.

Date	Location	Data Source	Type of Record	Detail	Odometer
09/27/2010	Alberta, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
09/27/2010	Alberta, Canada	Motor Vehicle Dept.	Canadian Renewal	First Owner Reported	
04/04/2011	Alberta, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
04/21/2011	Calgary, Alberta, Canada	Northwest Acura	Service Record	Vehicle serviced	6,841 KM
02/18/2012	Calgary, Alberta, Canada	Northwest Acura	Service Record	Vehicle serviced	20,791 KM
02/22/2012	Alberta, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
09/15/2012	Calgary, Alberta, Canada	Northwest Acura	Service Record	Vehicle serviced	40,745 KM
02/27/2013	Alberta, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
12/11/2013	Alberta, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
02/07/2014	Alberta, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	

05/01/2014	Calgary, Alberta, Canada	Northwest Acura	Service Record	Vehicle serviced	74,701 KM
12/02/2014	Calgary, Alberta, Canada	Service Facility	Service Record	Vehicle serviced	91,305 KM
12/04/2014	Alberta, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
10/15/2015	Alberta, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
01/11/2016	Alberta, Canada	Insurance Records	Collision claim		
01/11/2016	Calgary, Alberta, Canada	Insurance Records	Estimate Repair	Rear Center	110,362 KM
10/21/2017	Alberta, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
07/20/2018	Calgary, Alberta, Canada	Adair Auto Repair	Service Record	Vehicle serviced	146,280 KM
06/04/2019	Calgary, Alberta, Canada	Silverhill Acura	Service Record	Vehicle serviced	156,293 KM
08/06/2019	Alberta, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
10/10/2019	Alberta, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	

Accident, Collision and Damage Detail

If the vehicle has had any history of accidents, collisions or damage in either Canada or the U.S., the records are outlined in this section. This report also includes claims and estimates from ICBC.

VIN: 2HNYD2H69AH003868

Police Reported Accidents

Incident Date	Location	Detail
No police reported accidents found		

Accident/Damage Estimates

Accident estimate records are generated by collision estimating facilities from the process of estimating the amount and extent of damage to a vehicle. Estimates in some cases have associated insurance claims.

Incident Date	Location	Estimate Date	Type of Record	Detail	Amount	Odometer
01/11/2016	Calgary, Alberta, Canada	01/11/2016	Estimate Repair	Rear Center	$4,685.37	110,362 KM

Insurance Claims

The insurance claims identified in this report do not include any medical pay-outs, damage to other vehicles, damage to property, towing, rental cars, or any other incidental damages.

Incident Date	Location	Type of Claim	Detail	Amount	Odometer
01/11/2016	Alberta, Canada	Collision claim		$420.00	

Other Damage Records

Record Date	Location	Type of Record	Detail	Odometer
No other damage records found				

Lien Status

This section lists the provinces and territories where we searched for or found a security interest registered against the vehicle (lien). If a lien is found, further details will appear at the end of the report.

Province	Lien
Alberta	No lien found

CARFAX Canada Canadian Lien Guarantee

Our search results accurately reflect the government records of each personal property and security registry in Canada that is searched at the time the search request is made. If for some reason our search report fails to accurately reflect the Canadian enforceable lien status of a vehicle

Canadian Registration

This section details where in Canada the vehicle is now or has ever been registered, as well as the status (Inspection Required, Normal, Non-repairable, Rebuilt, Salvage, Stolen) of the vehicle in those jurisdictions.

Jurisdiction	Branding	Detail
Alberta	**NORMAL**	**This vehicle has been registered as Normal in this jurisdiction.**
British Columbia	Not found	
Manitoba	Not found	
New Brunswick	Not found	
Newfoundland	Not found	
Nova Scotia	Not found	
Northwest Territories	Not found	
Nunavut	Not found	
Ontario	Not found	
Prince Edward Island	Not found	
Quebec	Not found	
Saskatchewan	Not found	
Yukon Territories	Not found	

Stolen Vehicle Check

This section outlines data from the Canadian Police Information Centre (CPIC), which is operated by the RCMP under the stewardship of National Police Services, on behalf of the Canadian law enforcement community.

Stolen Vehicle Check
Not declared stolen.

Import Records

If the vehicle has been imported, you will find the details below.

Import Records
No vehicle import records found

United States Vehicle History

In addition to information about the vehicle's history in Canada, CARFAX Canada also searches for information about the vehicle's history in the United States. If we discover any events in the U.S., you will find them below. Details about accidents, collisions and damage, or any import records will appear in the preceding sections of your report.

U.S. History Records
No U.S. history records found

Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact ACURA or visit Acura's website.

Service History

These are records of service performed on the vehicle. These are the records reported to CARFAX Canada when this report was run – it is possible that service has occurred that is not captured here.

Date	Address	Data Source	Type of Record	Detail	Odometer
04/21/2011	Calgary, Alberta, Canada	Northwest Acura	Service Record	Vehicle serviced	6,841 KM
02/18/2012	Calgary, Alberta, Canada	Northwest Acura	Service Record	Vehicle serviced	20,791 KM
09/15/2012	Calgary, Alberta, Canada	Northwest Acura	Service Record	Vehicle serviced	40,745 KM
05/01/2014	Calgary, Alberta, Canada	Northwest Acura	Service Record	Vehicle serviced	74,701 KM
12/02/2014	Calgary, Alberta, Canada	Service Facility	Service Record	Vehicle serviced	91,305 KM
07/20/2018	Calgary, Alberta, Canada	Adair Auto Repair	Service Record	Vehicle serviced Brake pads replaced Brake fluid checked Brake fluid flushed/changed Brakes checked	146,280 KM
06/04/2019	Calgary, Alberta, Canada	Silverhill Acura	Service Record	Vehicle serviced Maintenance inspection completed Oil pump seal replaced Timing belt replaced	156,293 KM

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts.

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner.
The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim.
In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.
Consumers are encouraged to read ICBC's full statement of limitations at http://apps.icbc.com/registration/vchr/Limitation.html.
ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

CARFAX Canada One Owner™ Badge

The CARFAX Canada One Owner™ badge that appears in this vehicle history report is based on the registration information reported to CARFAX Canada and available for disclosure as of the date and time that this report was generated. The CARFAX Canada One Owner™ badge is available for personal and commercial CARFAX Canada that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI. By using this vehicle history report, you acknowledge and agree that there may be ownership events and/or other information that apply to this vehicle that are not reflected in this report.

CARFAX CANADA © Copyright 2005 - 2020 CARFAX Canada ULC. All rights reserved.

Information on Reports

Conditions of Use

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

Please note CARPROOF recently changed its name to CARFAX Canada!

CUSTOMER #: N/A

351990

INTERNAL

HARMONY HONDA

2550 Enterprise Way Kelowna, BC V1X 7X5
Service Direct: (250) 860-6530
Email:service@harmonyhonda.com
GST: 101447027RT0001

HARMONY HONDA
2550 ENTERPRISE WAY
KELOWNA, BC V1X 7X5

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 1240 RANDY KLYM

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
BLACK	10	ACURA MDX	2HNYD2H69AH003868		163539/163539	TU6869

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 21MAR20		0.00	CASH	21MAR20

R.O. OPENED	READY	OPTIONS:
11:24 10MAR20	09:03 21MAR20	STK:U6869 DLR:2021 ENG:3.7_Liter TRN:6_Speed_Automatic

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
A PERFORM USED CAR SAFETY INSPECTION			
SAFETY PERFORM USED CAR SAFETY INSPECTION			
1093 IUVH 1.50		210.00	210.00
1 15400-RTA-003 2 OIL FILTER CARTRI	10.92	10.92	10.92
1 94109-14000 8 WASHER DRAIN 14MM	1.00	1.00	1.00
5 020HO 0W20 SYTH OIL	5.80	5.80	29.00
PARTS: 40.92 LABOR: 210.00 OTHER: 0.00 TOTAL LINE A:			250.92
163539 1.50			
**********			
B PROVINCIAL INSPECTION - ALBERTA			
OOP PROVINCIAL INSPECTION			
1093 IUVH 0.50		70.00	70.00
DECAL OUT OF PROVINCE WINDSHIELD DECAL		7.00	7.00
PARTS: 0.00 LABOR: 70.00 OTHER: 7.00 TOTAL LINE B:			77.00
163539 0.50			
**********			
C PERFORM ACURA RECALL			
RECALL PERFORM HONDA RECALL			
1093 IUVH 0.00		0.00	0.00
**********			
D** REPLACE FRONT ROTORS			
CAUSE: REPLACE BRAKE PADS AND MACHINE FRONT ROTORS			
FBRK FRONT DISK BRAKES			
1093 IUVH 1.20		181.88	181.88
2 45251-STX-H01 A DISK FR BRAKE(17I	140.86	140.86	281.72
PARTS: 281.72 LABOR: 181.88 OTHER: 0.00 TOTAL LINE D:			463.60
163539 1.20			
**********			
E** REPLACE REAR BRAKE ROTORS			
CAUSE: REPLACE REAR BRAKE PADS AND MACHINE ROTORS			
RBRK REPLACE REAR BRAKES			
1093 IUVH 1.20		181.88	181.88
2 42510-TK8-A01 F DRUM IN DISK RR B	140.86	140.86	281.72
PARTS: 281.72 LABOR: 181.88 OTHER: 0.00 TOTAL LINE E:			463.60

TEXTING DISCLAIMER: Harmony Honda has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

I understand that Honda, its affiliates, dealers and service providers collect, use and disclose my personal information for the purposes of (i) completing my purchase, finance or lease transaction; (ii) maintaining my warranty and customer service records; (iii) conducting customer service campaigns; ((iv) providing me with marketing information; and (v) for legal and other business purposes. I consent to Honda, its affiliates, dealers and service providers contacting me by telephone or sending commercial electronic messages to me, including email and text messages. I can contact Honda at 1-888-946-6329 or 180 Honda Boulevard, Markham, Ontario L6C 0H9, and my dealer if I no longer consent to these uses and to update or correct my personal information.

x_____
CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
TAX	
PLEASE PAY THIS AMOUNT	

PARTS & SERVICE HOURS: MONDAY - FRIDAY 7:30 AM - 5:30 PM SATURDAY 8:00 AM - 4:30 PM

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2CE - IMAGING

INTERNAL COPY

CUSTOMER #: N/A

351990

INTERNAL

HARMONY HONDA

HARMONY HONDA
2550 ENTERPRISE WAY
KELOWNA, BC V1X 7X5

PAGE 2

2550 Enterprise Way Kelowna, BC V1X 7X5
Service Direct: (250) 860-6530
Email:service@harmonyhonda.com
GST: 101447027RT0001

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 1240 RANDY KLYM

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
BLACK	10	ACURA MDX	2HNYD2H69AH003868		163539/163539	TU6869

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 21MAR20		0.00	CASH	21MAR20

R.O. OPENED	READY	OPTIONS:
11:24 10MAR20	09:03 21MAR20	STK:U6869 DLR:2021 ENG:3.7_Liter TRN:6_Speed_Automatic

LINE OPCODE TECH TYPE HOURS		LIST	NET	TOTAL
163539 1.20				
**********				
F** 4 GOODYEARS 1206				
MOUNT4HP MOUNT AND BALANCE 4 18" PLUS TIRES				
1093 IUVH 1.00			122.88	122.88
WW WHEEL WEIGHT CHARGE			2.00	2.00
4 706068163 GOODYEAR EAGLE 255/88R18		247.75	247.75	991.00
4 TDF Tire Levy		5.00	5.00	20.00
PARTS: 991.00 LABOR: 122.88 OTHER: 22.00	TOTAL LINE F:			1135.88
163539 1.00				
**********				
G** WIPER BLADES				
BLADES WIPER BLADES				
1093 IUVH 0.00			0.00	0.00
1 76620-SHJ-A01 F BLADE WSHLD WIPER		25.95	25.95	25.95
1 76630-S3V-A11 A BLADE WSHLD WIPER		34.74	34.74	34.74
1 76622-S50-003 F BLADE RUB 300MM		9.80	9.80	9.80
PARTS: 70.49 LABOR: 0.00 OTHER: 0.00	TOTAL LINE G:			70.49
**********				
H** REPLACE BATTERY				
BATT REPLACE BATTERY				
1093 IUVH 0.20			28.00	28.00
BATT BATTERY RECYCLING FEE			5.00	5.00
1 31500-SD4-H650 BATTERY24F675CCA		177.99	177.99	177.99
PARTS: 177.99 LABOR: 28.00 OTHER: 5.00	TOTAL LINE H:			210.99
163539 0.20				
**********				
I** REPLACE BATTERY TERMINAL				
GEN GENERAL REPAIR				
1093 IUVH 0.40			56.00	56.00
1 HW2 HARDWARE KIT		5.75	5.75	5.75
PARTS: 5.75 LABOR: 56.00 OTHER: 0.00	TOTAL LINE I:			61.75
163539 0.40				
**********				

TEXTING DISCLAIMER: Harmony Honda has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

I understand that Honda, its affiliates, dealers and service providers collect, use and disclose my personal information for the purposes of (i) completing my purchase, finance or lease transaction; (ii) maintaining my warranty and customer service records; (iii) conducting customer service campaigns; ((iv) providing me with marketing information; and (v) for legal and other business purposes. I consent to Honda, its affiliates, dealers and service providers contacting me by telephone or sending commercial electronic messages to me, including email and text messages. I can contact Honda at 1-888-946-6329 or 180 Honda Boulevard, Markham, Ontario L6C 0H9, and my dealer if I no longer consent to these uses and to update or correct my personal information.

x_____
CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
TAX	
PLEASE PAY THIS AMOUNT	

PARTS & SERVICE HOURS: MONDAY - FRIDAY 7:30 AM - 5:30 PM SATURDAY 8:00 AM - 4:30 PM

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2CE - IMAGING

INTERNAL COPY

CUSTOMER #: N/A

351990

INTERNAL

HARMONY HONDA

HARMONY HONDA
2550 ENTERPRISE WAY
KELOWNA, BC V1X 7X5

PAGE 3

2550 Enterprise Way Kelowna, BC V1X 7X5
Service Direct: (250) 860-6530
Email:service@harmonyhonda.com
GST: 101447027RT0001

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 1240 RANDY KLYM

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
BLACK	10	ACURA MDX	2HNYD2H69AH003868		163539/163539	TU6869

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 21MAR20		0.00	CASH	21MAR20

R.O. OPENED	READY	OPTIONS:
11:24 10MAR20	09:03 21MAR20	STK:U6869 DLR:2021 ENG:3.7_Liter TRN:6_Speed_Automatic

LINE OPCODE TECH TYPE HOURS		LIST	NET	TOTAL
J** INSTALL FRONT PLATE BRACKET				
GEN GENERAL REPAIR				
1093 IUVH 0.00			0.00	0.00
1 71180-STX-A01	BASE FR LIC PLATE	17.79	17.79	17.79
PARTS: 17.79 LABOR: 0.00 OTHER: 0.00			TOTAL LINE J:	17.79
**********				
K** REPLACE DRIVERS MASTER POWER WINDOW SWITCH 212.00				
GEN GENERAL REPAIR				
1093 IUVH 0.60			84.00	84.00
1 35750-STX-A01ZA	MASTER POWER SWITCH	128.46	128.46	128.46
PARTS: 128.46 LABOR: 84.00 OTHER: 0.00			TOTAL LINE K:	212.46
163539 0.60				
**********				
L** REMOVE REMOTE START				
GEN GENERAL REPAIR				
1093 IUVH 0.80			112.00	112.00
PARTS: 0.00 LABOR: 112.00 OTHER: 0.00			TOTAL LINE L:	112.00
163539 0.80				
**********				
M** REPKACE TIMING BELT, TENSIONER, AND OIL PUMP SEALS				
TBELTV6 REPLACE TIMING BELT, INSPECT WATER PUMP AND HYDRAULIC TENSIONER FOR LEAKS				
1093 IUVH 6.50			910.00	910.00
1 14400-RCA-A01 2	BELT TIMING 197YU	132.23	132.23	132.23
1 14520-RCA-A01 2	TENSIONER COMP T/	237.29	237.29	237.29
1 15115-P8A-A01 2	PKG OIL HOLE	7.12	7.12	7.12
1 15221-RYE-A01 2	RING O	8.00	8.00	8.00
1 91212-5MR-A01 2	OIL SEAL 41X56X7	27.49	27.49	27.49
1 91319-PR3-003 A	O-RING 13X1 5	11.49	11.49	11.49
1 36172-P8A-A01 2	PACKING BASE SOL	16.05	16.05	16.05
1 15825-P8A-A01 2	FILTER ASSY SPOOL	28.28	28.28	28.28
PARTS: 467.95 LABOR: 910.00 OTHER: 0.00			TOTAL LINE M:	1377.95
163539 6.50				
**********				

TEXTING DISCLAIMER: Harmony Honda has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

I understand that Honda, its affiliates, dealers and service providers collect, use and disclose my personal information for the purposes of (i) completing my purchase, finance or lease transaction; (ii) maintaining my warranty and customer service records; (iii) conducting customer service campaigns; ((iv) providing me with marketing information; and (v) for legal and other business purposes. I consent to Honda, its affiliates, dealers and service providers contacting me by telephone or sending commercial electronic messages to me, including email and text messages. I can contact Honda at 1-888-946-6329 or 180 Honda Boulevard, Markham, Ontario L6C 0H9, and my dealer if I no longer consent to these uses and to update or correct my personal information.

x_____
CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
TAX	
PLEASE PAY THIS AMOUNT	

PARTS & SERVICE HOURS: MONDAY - FRIDAY 7:30 AM - 5:30 PM SATURDAY 8:00 AM - 4:30 PM

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2CE - IMAGING

INTERNAL COPY

CUSTOMER #: N/A

351990

INTERNAL

HARMONY HONDA

2550 Enterprise Way Kelowna, BC V1X 7X5
Service Direct: (250) 860-6530
Email:service@harmonyhonda.com
GST: 101447027RT0001

HARMONY HONDA
2550 ENTERPRISE WAY
KELOWNA, BC V1X 7X5

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 1240 RANDY KLYM

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
BLACK	10	ACURA MDX	2HNYD2H69AH003868		163539/163539	TU6869

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 21MAR20		0.00	CASH	21MAR20

R.O. OPENED	READY	OPTIONS:
11:24 10MAR20	09:03 21MAR20	STK:U6869 DLR:2021 ENG:3.7_Liter TRN:6_Speed_Automatic

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
N** AVR TEST AND REPORT			
DIAG DIAGNOSE CUSTOMER COMPLAINT -			
1093 IUVH 0.60		84.00	84.00
PARTS: 0.00 LABOR: 84.00 OTHER: 0.00 TOTAL LINE N:			84.00
163539 0.60 PERFORMED FULL AVR AND FOUND NO STARTING OR CHARGING ISSUES. NO FURTHER WORK REQUIRED.			
**********			

COST/SALE/COMP TOT: 207954 453843 0

TEXTING DISCLAIMER: Harmony Honda has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

I understand that Honda, its affiliates, dealers and service providers collect, use and disclose my personal information for the purposes of (i) completing my purchase, finance or lease transaction; (ii) maintaining my warranty and customer service records; (iii) conducting customer service campaigns; ((iv) providing me with marketing information; and (v) for legal and other business purposes. I consent to Honda, its affiliates, dealers and service providers contacting me by telephone or sending commercial electronic messages to me, including email and text messages. I can contact Honda at 1-888-946-6329 or 180 Honda Boulevard, Markham, Ontario L6C 0H9, and my dealer if I no longer consent to these uses and to update or correct my personal information.

x_____
CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOUR AMOUNT	2040.64
PARTS AMOUNT	2463.79
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	34.00
TOTAL CHARGES	4538.43
LESS INSURANCE	0.00
TAX	0.00
PLEASE PAY THIS AMOUNT	4538.43

PARTS & SERVICE HOURS: MONDAY - FRIDAY 7:30 AM - 5:30 PM SATURDAY 8:00 AM - 4:30 PM

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2CE - IMAGING

INTERNAL COPY

Honda Multi-Point Vehicle Inspection Checklist

HARMONY Honda

HONDA GENUINE PARTS & SERVICE

BOOK YOUR NEXT SERVICE APPOINTMENT ONLINE.

R/O Number: 351990
Customer Name: ,
Odometer: 163539
Next Service Due: A / 0 ☑ B ☐ 9 ☐
Advisor: Mykeal Antaloczy
Technician: Karlin Gamache

Not Applicable or Not Checked

Satisfactory | May require future attention | Requires immediate attention

Main Item A / 0 / B

Under Hood

Engine Oil	✓
Windshield Washer Fluid Level	✓
Coolant level	✓
Power Steering Fluid	✓
Brake Fluid Level	✓
Transmission Fluid Level	✓
External Drive Belts and Radiator Hoses	✓
Air/Cabin/Dust & Pollen Filter	✓

Safety

Battery Condition (Date of Mfr: _____)	✓
Genuine Floor Mats Installed	✓
Anchored properly & 1 mat only in driver footwell	✓

Tires

All Season Tires: 6/32 or more | 4/32 to 5/32 | 3/32 or less
Winter Tires: 9/32 or more | 6/32 to 8/32 | 5/32 or less

Tire Condition LF: Tread 100 /32nds Wear Pattern	✓
Tire Condition RF: Tread 100 /32nds Wear Pattern	✓
Tire Condition LR: Tread 100 /32nds Wear Pattern	✓
Tire Condition RR: Tread 100 /32nds Wear Pattern	✓

Recommended: Rotation ☐ Alignment ☐ Replacement ☐
Seasonal Tire Changeover Recommended ☐

Interior / Exterior

Headlights (High / Low beam)	✓
Taillights (Running / Brake)	✓
Turn Signals (Hazards)	✓
Horn	✓
Parking Brake	✓
Windshield Washer Operation / Wipers	✓
Windshield Condition	✓
Clutch Operation (if applicable)	✓
Interior Lights	✓

Under Vehicle

Brakes / Lines / Hoses / Parking Brake Cable	✓
Shock Absorber / Struts / Suspension	✓
Tie Rod Ends, Steering Gear Box, Boots	✓
Driveshaft Boots / Bands	✓
Exhaust System / Heat Shields	✓
Catalytic Converter	✓
Fuel Lines and Connections	✓

Please Indicate Areas of External Damage or Wear



Main Item B & Sub-Item 9

Brake Condition

Pad Measurement: 5mm or more | 3-4mm | 2mm or less

Left Front: _____mm 75 %	✓
Right Front: _____mm 75 %	✓
Left Rear: _____mm 75 %	✓
Right Rear: _____mm 75 %	✓
Front Rotors: _____mm ☐ Turn ☐ Replace	✓
Rear Rotors: _____mm ☐ Turn ☐ Replace	✓
Rear Drums: _____mm ☐ Turn ☐ Replace	✓

Brake Service

A) Brake Lines / Hoses	✓
B) Brake Line Connections	✓
C) Honda M-77 Brake Caliper Assembly Paste	✓
D) Caliper Pin Boots	✓
E) Piston Seal	✓
F) Caliper Pins	✓
G) Pad Return Springs	✓



Maintenance Light Reset ☑ Yes ☐ N/A
Any Outstanding Recalls / Product updates? ☐ Yes ☑ No

Comments:

Lowest Price Guarantee on Tires* | Lifetime Brake Pad Guarantee* | Lowest Price Guarantee on OW-20 Oil Changes*

** Some conditions and restrictions apply. Ask your Honda Service Advisor for complete details.*