HARMONY Honda

THE HARMONY GUARANTEE - WE GUARANTEE YOU'LL LIKE YOUR PRE-OWNED VEHICLE

1. No Documentation Fees or Hidden Charges
2. 120 Point Inspection on Every Pre-Owned Vehicle
3. 30 Day 2500 KM Exchange Policy
4. Complete Vehicle Detail
5. CarProof Vehicle History Report
6. Full Tank of Gas

2002 HONDA ACCORD

STOCK #: 19789B

VIN NUMBER: 1HGCG56762A818020

COLOUR: SILVER

ODOMETER: 199,128

SEATS: 5

ENGINE: 2.3L/4CYL

TRANSMISSION: AUTO

Front Brake Life: 40 %

Rear Brake Life: 40 %

Front Tire Tread Life: 60 %

Rear Tire Tread Life: 60 %

WHAT MAKES THIS VEHICLE UNIQUE?

- BC VEHICLE !!
- NEW TIMING BELT !!
- NEW SERPENTINE BELT !!
- FRONT WHEEL DRIVE !!
- WINTERS 60% AND 50%

For more information on this vehicle visit www.harmonyhonda.com

PRICE $7,900

2550 Enterprise Way
Kelowna, BC
V1X 7X5
PH: 250-860-6500

Monday - Thursday 8am - 7pm
Friday - Saturday 8am - 6pm
Closed Sunday

www.harmonyhonda.com

HARMONY Honda

USED CAR CHECK-IN SHEET

SALES REP: Jessica.

YEAR	MAKE	TRIM	ENGINE DISP.	# CYL	ENG HP	MILEAGE	STOCK #
2002	Honda	SE	2.3	4	150	199128	19789B
	MODEL Accord	BODY Sedan					

VIN	TRANS.	COLOUR - EXT.	COLOUR - INT.
1HGCG56762A818020	Auto	Silver	Gray

EQUIPMENT

- ✓ AM/FM Stereo
- ✓ AM/FM Stereo w/CD
- X DVD System (RES)
- X Bluetooth
- ✓ Air Conditioning
- ✓ Cruise Control
- ✓ Tilt Steering
- X Leather Interior
- ✓ Power Windows/Mirrors
- ✓ Power Door Locks
- X Power Trunk
- ✓ Floor Mats
- ✓ Alloy Wheels
- ✓ Remote Keyless Entry
- X Power Driver's Seat
- X Dual Power Seats
- ✓ ~~Cooled Seats~~ / Heated Seats
- X Push Button Start
- X Navigation System
- X Backup Camera
- X Blind Spot Monitors
- X Rear Spoiler
- ✓ Sunroof / ~~Panoramic Roof~~
- X Fog Lights
- X Tire Pressure Monitoring System (TPMS)
- ✓ Driver's Side Airbags (SIR)
- ✓ Dual Airbags (SIR)
- X Side Airbags
- X Side Curtain Airbags
- ✓ Anti-Lock Brakes / VSA
- ✓ Anti-Theft Device
- ___ Drive Train - 4WD / AWD / (FWD) / RWD / 4X4
- 5 Seats (# of)
- ___ Accessories
- ___ Other
- ___ Other

X Active Safety Radars / Driver Assist Technologies: X

FACTORY WARRANTY EXPIRES: X DATE OR X MILEAGE

DECLARATIONS

Any Accidents/Damage	✓ Yes	___ No
Damage Over $2000	✓ Yes	___ No
Ex-Lease	___ Yes	✓ No
Ex-Rental	___ Yes	✓ No
Out of Province	___ Yes	✓ No
If Yes, Province:		

OTHER INFORMATION

Extra Keys	___ Yes	___ No
Extra Remotes	___ Yes	___ No
Owner's Manual	___ Yes	X No
Radio Code		
Key Code		

VEHICLE HISTORY

What makes this vehicle unique?

(I.E.: Traded in on? # of owners? Purpose of vehicle use? Previous customer info? No accidents? Bought & serviced at Harmony?)

1) BC vehicle
2) Traded in on a Honda CR-V ✓
3) New Timing Belt
4) New Serpentine Belt
5) Winters 60% + 50%

SETS OF TIRES

2nd ✓ Yes ___ No

ON RIMS? ___ Yes X No

Front Tires	60 %	Front Brakes	40 %
Rear Tires	60 %	Rear Brakes	40 %

Price $ 7,900

	✓	#
Safety	✓	
Detail	✓	
Online	✓	

QF10c Rev.F
Sep-17

CARFAX CANADA

VERIFIED BC VEHICLE HISTORY REPORT

VEHICLE DETAILS:
VIN: 1HGCG56762A818020
Year/Make/Model: 2002 HONDA ACCORD SE
Body Style: SEDAN
Country of Assembly: United States
Cylinders: 4
Fuel Type: Gas

REPORT DETAILS:
Report Number: 28145496
Report Date: 5/8/2020 07:09 PM EST
Report Status: Complete
Reference:

REPORT SUMMARY

Accidents / Damage:	Damage records found
Lien Records:	No lien records found
Canadian Registration:	British Columbia (Normal)
Stolen Status:	Not actively declared stolen
U.S. History:	No U.S. history found
Recalls:	No information available
Service History:	2 record(s) found

QUESTIONS?
WE'RE HERE TO HELP.
CALL
1.866.835.8612
EMAIL
SUPPORT@CARFAX.CA

Report Findings in Chronological Order

Below are all records for the vehicle, listed in the order that they occurred.

Date	Location	Data Source	Type of Record	Detail	Odometer
07/31/2002	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
07/31/2002	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	First Owner Reported	
12/12/2002	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
12/12/2003	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
12/12/2004	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
12/12/2005	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
07/11/2006	British Columbia, Canada	Insurance Records	COLLISION	RIGHT REAR SIDE	
12/04/2006	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
12/15/2007	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
12/13/2008	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
12/19/2009	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	

Date	Location	Data Source	Type of Record	Detail	Odometer
12/18/2010	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
12/17/2011	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
12/15/2012	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
03/23/2013	British Columbia, Canada	Insurance Records	Estimate	RIGHT FRONT CORNER	
12/14/2013	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
12/13/2014	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
08/20/2015	British Columbia, Canada	Insurance Records	COLLISION	LEFT REAR CORNER	
09/10/2015	North Vancouver, British Columbia, Canada	Service Facility	Service Record	Vehicle serviced	149,815 KM
12/19/2015	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
08/05/2017	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
10/18/2017	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
12/09/2017	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
07/28/2018	British Columbia, Canada	Insurance Records	COLLISION	LEFT REAR CORNER	
12/09/2018	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
08/11/2019	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
08/11/2019	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	New Owner Reported	
08/21/2019	Vancouver, British Columbia, Canada	Carter Honda	Service Record	Vehicle serviced	190,561 KM
09/01/2019	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
09/01/2019	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	New Owner Reported	

Accident, Collision and Damage Detail

If the vehicle has had any history of accidents, collisions or damage in either Canada or the U.S., the records are outlined in this section. This report also includes claims and estimates from ICBC.

VIN: 1HGCG56762A818020

Police Reported Accidents

Incident Date	Location	Detail
No police reported accidents found		

Accident/Damage Estimates

Accident estimate records are generated by collision estimating facilities from the process of estimating the amount and extent of damage to a vehicle. Estimates in some cases have associated insurance claims.

Incident Date	Location	Estimate Date	Type of Record	Detail	Amount	Odometer
03/23/2013	British Columbia, Canada		Estimate	RIGHT FRONT CORNER	$502.85	

Insurance Claims

The insurance claims identified in this report do not include any medical pay-outs, damage to other vehicles, damage to property, towing, rental cars, or any other incidental damages.

Incident Date	Location	Type of Claim	Detail	Amount	Odometer
07/11/2006	British Columbia, Canada	COLLISION	RIGHT REAR SIDE	$1,253.61	
08/20/2015	British Columbia, Canada	COLLISION	LEFT REAR CORNER	$615.79	
07/28/2018	British Columbia, Canada	COLLISION	LEFT REAR CORNER	$1,199.26	

Other Damage Records

Record Date	Location	Type of Record	Detail	Odometer
No other damage records found				

Lien Status

This section lists the provinces and territories where we searched for or found a security interest registered against the vehicle (lien). If a lien is found, further details will appear at the end of the report.

Province	Lien
British Columbia	No lien found

CARFAX Canada Canadian Lien Guarantee

Our search results accurately reflect the government records of each personal property and security registry in Canada that is searched at the time the search request is made. If for some reason our search report fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian ($5,000.00), whichever is lower.

Canadian Registration

This section details where in Canada the vehicle is now or has ever been registered, as well as the status (Inspection Required, Normal, Non-repairable, Rebuilt, Salvage, Stolen) of the vehicle in those jurisdictions.

Jurisdiction	Branding	Detail
Alberta	Not found	
British Columbia	**NORMAL**	**This vehicle has been registered as Normal in this jurisdiction.**
Manitoba	Not found	
New Brunswick	Not found	
Newfoundland	Not found	
Nova Scotia	Not found	
Northwest Territories	Not found	
Nunavut	Not found	
Ontario	Not found	
Prince Edward Island	Not found	
Quebec	Not found	
Saskatchewan	Not found	
Yukon Territories	Not found	

Stolen Vehicle Check

This section outlines data from the Canadian Police Information Centre (CPIC), which is operated by the RCMP under the stewardship of National Police Services, on behalf of the Canadian law enforcement community.

Stolen Vehicle Check
Not declared stolen.

Import Records

If the vehicle has been imported, you will find the details below.

Import Records
No vehicle import records found

United States Vehicle History

In addition to information about the vehicle's history in Canada, CARFAX Canada also searches for information about the vehicle's history in the United States. If we discover any events in the U.S., you will find them below. Details about accidents, collisions and damage, or any import records will appear in the preceding sections of your report.

U.S. History Records

No U.S. history records found

Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact HONDA or visit Honda's website.

Service History

These are records of service performed on the vehicle. These are the records reported to CARFAX Canada when this report was run – it is possible that service has occurred that is not captured here.

Date	Address	Data Source	Type of Record	Detail	Odometer
09/10/2015	North Vancouver, British Columbia, Canada	Service Facility	Service Record	Vehicle serviced	149,815 KM
08/21/2019	Vancouver, British Columbia, Canada	Carter Honda	Service Record	Vehicle serviced Pre-delivery inspection completed	190,561 KM

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts.

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner.
The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim.
In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.
Consumers are encouraged to read ICBC's full statement of limitations at http://apps.icbc.com/registration/vchr/Limitation.html.
ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

CARFAX CANADA © Copyright 2005 - 2020 CARFAX Canada ULC. All rights reserved.

Information on Reports

Conditions of Use

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

Please note CARPROOF recently changed its name to CARFAX Canada!

CUSTOMER #: N/A

354342

INTERNAL

HARMONY HONDA

2550 Enterprise Way Kelowna, BC V1X 7X5
Service Direct: (250) 860-6530
Email:service@harmonyhonda.com
GST: 101447027RT0001

HARMONY HONDA
2550 ENTERPRISE WAY
KELOWNA, BC V1X 7X5

PAGE 1

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 930 930 930

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
	02	HONDA Accord	1HGCG56762A818020		199128/199128	19789B

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 18MAY20		0.00	CASH	21MAY20

R.O. OPENED	READY	OPTIONS:
13:19 14MAY20	14:41 21MAY20	STK:19789B DLR:1108 ENG:2.3_Liter

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
A PERFORM USED CAR SAFETY INSPECTION			
SAFETY PERFORM USED CAR SAFETY INSPECTION			
1093 IUVH 1.50		210.00	210.00
1 15400-RTA-003 2 OIL FILTER CARTRI	10.92	10.92	10.92
5 520HO 5W20 OIL	4.32	4.32	21.60
1 94109-14000 8 WASHER DRAIN 14MM	1.00	1.00	1.00
PARTS: 33.52 LABOR: 210.00 OTHER:	0.00	TOTAL LINE A:	243.52
199128 1.50			
**********			
C PERFORM HONDA RECALL			
RECALL PERFORM HONDA RECALL			
1093 IUVH 0.00		0.00	0.00
**********			
D** REPLACE TIMING BELT AND INSPECT WATER PUMP - 4 CYLINDER MODELS			
TBELT REPLACE TIMING BELT AND INSPECT WATER PUMP - 4 CYLINDER MODELS			
1093 IUVH 3.00		251.57	251.57
1 13405-PAA-A03 2 BELT TIMING BALAN	52.35	52.35	52.35
1 14400-PAA-A02 2 BELT TIMING 112RU	121.08	121.08	121.08
PARTS: 173.43 LABOR: 251.57 OTHER:	0.00	TOTAL LINE D:	425.00
199128 3.00			
**********			
E** REPLACE DISTRIBUTOR O-RING			
GEN GENERAL REPAIR			
1093 IUVH 1.40		196.00	196.00
1 30110-PC6-005 2 O-RING	5.93	5.93	5.93
PARTS: 5.93 LABOR: 196.00 OTHER:	0.00	TOTAL LINE E:	201.93
199128 1.40			
**********			
F** REPLACE SERPENTINE BELT			
SERP REPLACE SERPENTINE BELT			
1093 IUVH 0.00		0.00	0.00
1 38920-PAA-A03 2 BELT COMPR (6PK11	65.16	65.16	65.16
1 56992-P0A-J03 2 BELT P/S P (4PK10	34.89	34.89	34.89

TEXTING DISCLAIMER: Harmony Honda has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

I understand that Honda, its affiliates, dealers and service providers collect, use and disclose my personal information for the purposes of (i) completing my purchase, finance or lease transaction; (ii) maintaining my warranty and customer service records; (iii) conducting customer service campaigns; ((iv) providing me with marketing information; and (v) for legal and other business purposes. I consent to Honda, its affiliates, dealers and service providers contacting me by telephone or sending commercial electronic messages to me, including email and text messages. I can contact Honda at 1-888-946-6329 or 180 Honda Boulevard, Markham, Ontario L6C 0H9, and my dealer if I no longer consent to these uses and to update or correct my personal information.

x_____
CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
TAX	
PLEASE PAY THIS AMOUNT	

PARTS & SERVICE HOURS: MONDAY - FRIDAY 7:30 AM - 5:30 PM SATURDAY 8:00 AM - 4:30 PM

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2CE - IMAGING

INTERNAL COPY

CUSTOMER #: N/A

354342

INTERNAL

HARMONY HONDA

2550 Enterprise Way Kelowna, BC V1X 7X5
Service Direct: (250) 860-6530
Email:service@harmonyhonda.com
GST: 101447027RT0001

HARMONY HONDA
2550 ENTERPRISE WAY
KELOWNA, BC V1X 7X5

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 930 930 930

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
	02	HONDA Accord	1HGCG56762A818020		199128/199128	19789B

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 18MAY20		0.00	CASH	21MAY20

R.O. OPENED	READY	OPTIONS:
13:19 14MAY20	14:41 21MAY20	STK:19789B DLR:1108 ENG:2.3_Liter

LINE OPCODE TECH TYPE HOURS			LIST	NET	TOTAL
PARTS: 100.05 LABOR: 0.00 OTHER:			0.00	TOTAL LINE F:	100.05
**********					
G** MAINTENANCE MINDER (2) CARS/4 CYL TRUCKS 101.88					
91HOZ205 MAINTENANCE MINDER (2) CARS/4 CYL TRUCKS					
101.88					
1093 IUVH 0.50				50.15	50.15
2 80291-S84-A01 2 FILTER ELEMENT			16.29	16.29	32.58
1 @17220-PAA-A00 AIR FILTER			19.14	19.14	19.14
PARTS: 51.72 LABOR: 50.15 OTHER:			0.00	TOTAL LINE G:	101.87
199128 0.30					
CHANGE ENGINE AIR FILTER AND CABIN AIR FILTER, INSPECT DRIVE BELT FOR WEAR					
CHANGE ENGINE AIR FILTER AND CABIN AIR FILTER, INSPECT DRIVE BELT FOR WEAR					
**********					
H** REPLACE REAR SWAY BAR LINKS					
GEN GENERAL REPAIR					
1093 IUVH 1.00				140.00	140.00
1 06523-S84-A00 2 STABI LINK KIT			171.25	171.25	171.25
PARTS: 171.25 LABOR: 140.00 OTHER:			0.00	TOTAL LINE H:	311.25
199128 1.00					
**********					
I** REAR BRAKE SERVICE					
RBSVC REAR BRAKE SERVICE					
1093 IUVH 0.50				70.00	70.00
1 HW2 HARDWARE KIT			5.75	5.75	5.75
1 CA66932 8 CONT/BRKE CLEANER			5.22	5.22	5.22
PARTS: 10.97 LABOR: 70.00 OTHER:			0.00	TOTAL LINE I:	80.97
199128 0.50					
**********					
J** MACHINE BRAKE ROTORS - FRONT					
MACH MACHINE BRAKE ROTORS					
1093 IUVH 1.20				168.00	168.00
1 HW2 HARDWARE KIT			5.75	5.75	5.75

TEXTING DISCLAIMER: Harmony Honda has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

I understand that Honda, its affiliates, dealers and service providers collect, use and disclose my personal information for the purposes of (i) completing my purchase, finance or lease transaction; (ii) maintaining my warranty and customer service records; (iii) conducting customer service campaigns; ((iv) providing me with marketing information; and (v) for legal and other business purposes. I consent to Honda, its affiliates, dealers and service providers contacting me by telephone or sending commercial electronic messages to me, including email and text messages. I can contact Honda at 1-888-946-6329 or 180 Honda Boulevard, Markham, Ontario L6C 0H9, and my dealer if I no longer consent to these uses and to update or correct my personal information.

x_____
CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
TAX	
PLEASE PAY THIS AMOUNT	

PARTS & SERVICE HOURS: MONDAY - FRIDAY 7:30 AM - 5:30 PM SATURDAY 8:00 AM - 4:30 PM

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2CE - IMAGING

INTERNAL COPY

CUSTOMER #: N/A

354342

INTERNAL

HARMONY HONDA

2550 Enterprise Way Kelowna, BC V1X 7X5
Service Direct: (250) 860-6530
Email:service@harmonyhonda.com
GST: 101447027RT0001

HARMONY HONDA
2550 ENTERPRISE WAY
KELOWNA, BC V1X 7X5

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 930 930 930

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
	02	HONDA Accord	1HGCG56762A818020		199128/199128	19789B

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 18MAY20		0.00	CASH	21MAY20

R.O. OPENED	READY	OPTIONS:
13:19 14MAY20	14:41 21MAY20	STK:19789B DLR:1108 ENG:2.3_Liter

LINE	OPCODE	TECH	TYPE	HOURS		LIST	NET	TOTAL
1	CA66932	8	CONT/BRKE CLEANER			5.22	5.22	5.22

PARTS: 10.97 LABOR: 168.00 OTHER: 0.00 TOTAL LINE J: 178.97
199128 1.20

****

COST/SALE/COMP TOT: 61825 164356 0

TEXTING DISCLAIMER: Harmony Honda has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

I understand that Honda, its affiliates, dealers and service providers collect, use and disclose my personal information for the purposes of (i) completing my purchase, finance or lease transaction; (ii) maintaining my warranty and customer service records; (iii) conducting customer service campaigns; ((iv) providing me with marketing information; and (v) for legal and other business purposes. I consent to Honda, its affiliates, dealers and service providers contacting me by telephone or sending commercial electronic messages to me, including email and text messages. I can contact Honda at 1-888-946-6329 or 180 Honda Boulevard, Markham, Ontario L6C 0H9, and my dealer if I no longer consent to these uses and to update or correct my personal information.

x_____
CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOUR AMOUNT	1085.72
PARTS AMOUNT	557.84
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	1643.56
LESS INSURANCE	0.00
TAX	0.00
PLEASE PAY THIS AMOUNT	1643.56

PARTS & SERVICE HOURS: MONDAY - FRIDAY 7:30 AM - 5:30 PM SATURDAY 8:00 AM - 4:30 PM

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2CE - IMAGING

INTERNAL COPY

Honda Multi-Point Vehicle Inspection Checklist

HARMONY Honda

HONDA GENUINE PARTS & SERVICE

BOOK YOUR NEXT SERVICE APPOINTMENT ONLINE.

R/O Number: 354342

Customer Name: ,

Odometer: 199128

Next Service Due: A / 0 ☑ B ☐ 9 ☐

Advisor: Mykeal Antaloczy

Technician: HOUSE, Karlin ...

Not Applicable or Not Checked

Satisfactory | May require future attention | Requires immediate attention

Main Item A / 0 / B

Under Hood

Engine Oil	✓
Windshield Washer Fluid Level	✓
Coolant level	✓
Power Steering Fluid	✓
Brake Fluid Level	✓
Transmission Fluid Level	✓
External Drive Belts and Radiator Hoses	✓
Air/Cabin/Dust & Pollen Filter	✓

Safety

Battery Condition (Date of Mfr: _____)	✓
Genuine Floor Mats Installed	✓
Anchored properly & 1 mat only in driver footwell	✓

Tires

All Season Tires: 6/32 or more | 4/32 to 5/32 | 3/32 or less

Winter Tires: 9/32 or more | 6/32 to 8/32 | 5/32 or less

Tire Condition LF: Tread 60 /32nds Wear Pattern	✓
Tire Condition RF: Tread 60 /32nds Wear Pattern	✓
Tire Condition LR: Tread 60 /32nds Wear Pattern	✓
Tire Condition RR: Tread 60 /32nds Wear Pattern	✓

Recommended: Rotation ☐ Alignment ☐ Replacement ☐

Seasonal Tire Changeover Recommended ☐

Interior / Exterior

Headlights (High / Low beam)	✓
Taillights (Running / Brake)	✓
Turn Signals (Hazards)	✓
Horn	✓
Parking Brake	✓
Windshield Washer Operation / Wipers	✓
Windshield Condition	✓
Clutch Operation (if applicable)	✓
Interior Lights	✓

Under Vehicle

Brakes / Lines / Hoses / Parking Brake Cable	✓
Shock Absorber / Struts / Suspension	✓
Tie Rod Ends, Steering Gear Box, Boots	✓
Driveshaft Boots / Bands	✓
Exhaust System / Heat Shields	✓
Catalytic Converter	✓
Fuel Lines and Connections	✓

Please Indicate Areas of External Damage or Wear



Main Item B & Sub-Item 9

Brake Condition

Pad Measurement: 5mm or more | 3-4mm | 2mm or less

Left Front: ____mm 40 %	✓
Right Front: ____mm 40 %	✓
Left Rear: ____mm 40 %	✓
Right Rear: ____mm 40 %	✓
Front Rotors: ____mm ☐ Turn ☐ Replace	✓
Rear Rotors: ____mm ☐ Turn ☐ Replace	✓
Rear Drums: ____mm ☐ Turn ☐ Replace	✓

Brake Service

A) Brake Lines / Hoses	✓
B) Brake Line Connections	✓
C) Honda M-77 Brake Caliper Assembly Paste	✓
D) Caliper Pin Boots	✓
E) Piston Seal	✓
F) Caliper Pins	✓
G) Pad Return Springs	✓



Maintenance Light Reset ☑ Yes ☐ N/A

Any Outstanding Recalls / Product updates? ☐ Yes ☑ No

Comments:

Lowest Price Guarantee on Tires* | Lifetime Brake Pad Guarantee* | Lowest Price Guarantee on 0W-20 Oil Changes*

** Some conditions and restrictions apply. Ask your Honda Service Advisor for complete details.*