HARMONY ACURA

THE HARMONY GUARANTEE - WE GUARANTEE YOU'LL LIKE YOUR PRE-OWNED VEHICLE

1. No Documentation Fees or Hidden Charges
2. 120 Point Inspection on Every Pre-Owned Vehicle
3. 30 Day 2500 KM Exchange Policy
4. Complete Vehicle Detail
5. CarProof Vehicle History Report
6. Full Tank of Gas

2010 HONDA CR-V

STOCK #: AU2573A

VIN NUMBER: 5J6RE4H77AL814383

COLOUR: BLUE

ODOMETER: 225,119

SEATS: 5

ENGINE: 2.4L/4CYL

TRANSMISSION: AUTO

Front Brake Life: 80 %

Rear Brake Life: 70 %

Front Tire Tread Life: 60 %

Rear Tire Tread Life: 40 %

WHAT MAKES THIS VEHICLE UNIQUE?

- ONE OWNER !!
- NEW BATTERY !!
- 4 WHEEL DRIVE !!
- BC VEHICLE !!

For more information on this vehicle visit **www.harmonyacura.com**

PRICE $12,900

2552 Enterprise Way
Kelowna, BC
V1X 7X5
PH: 250-861-3003

Monday - Friday 8am - 7pm
Saturday 9am - 6pm
Closed Sunday

www.harmonyacura.com

HARMONY ACURA

USED CAR CHECK-IN SHEET

SALES REP: Rory

YEAR	MAKE	TRIM	ENGINE DISP.	# CYL	ENG HP	MILEAGE	STOCK #
2010	Honda	EX-L Nav	2.4	4	180	225119	AU2573A
	MODEL CR-V	BODY SUV					

VIN	TRANS.	COLOUR - EXT.	COLOUR - INT.
5J6RE4H77AL814383	Auto	Blue	Black

EQUIPMENT

- ✓ AM/FM Stereo
- ✓ AM/FM Stereo w/CD
- ___ DVD System (RES)
- ✓ Bluetooth
- ✓ Air Conditioning
- ✓ Cruise Control
- ✓ Tilt Steering
- ✓ Leather Interior
- ✓ Power Windows/Mirrors
- ✓ Power Door Locks
- ___ Power Trunk
- ✓ Floor Mats
- ✓ Alloy Wheels
- ✓ Remote Keyless Entry
- ✓ Power Driver's Seat
- ___ Dual Power Seats
- ✓ ~~Cooled Seats~~ / Heated Seats
- ___ Push Button Start
- ✓ Navigation System
- ✓ Backup Camera
- ___ Blind Spot Monitors
- ___ Rear Spoiler
- ✓ Sunroof / Panoramic Roof
- ✓ Fog Lights
- ✓ Tire Pressure Monitoring System (TPMS)
- ✓ Driver's Side Airbags (SIR)
- ✓ Dual Airbags (SIR)
- ✓ Side Airbags
- ✓ Side Curtain Airbags
- ✓ Anti-Lock Brakes / VSA
- ✓ Anti-Theft Device
- ✓ Drive Train 4WD / AWD / FWD / RWD / 4X4
- ✓ Seats (# of) 5
- ✓ Accessories Hitch
- ___ Other
- ___ Other

___ Active Safety Radars / Driver Assist Technologies: _____

FACTORY WARRANTY EXPIRES: _____ DATE OR _____ MILEAGE

DECLARATIONS

Any Accidents/Damage	✓ Yes	___ No
Damage Over $2000	___ Yes	X No
Ex-Lease	___ Yes	X No
Ex-Rental	___ Yes	X No
Out of Province	___ Yes	X No
If Yes, Province:		

OTHER INFORMATION

Extra Keys	✓ Yes	___ No
Extra Remotes	✓ Yes	___ No
Owner's Manual	✓ Yes	___ No
Radio Code		
Key Code		

VEHICLE HISTORY

What makes this vehicle unique?

(I.E.: Traded in on? # of owners? Purpose of vehicle use? Previous customer info? No accidents? Bought & serviced at Harmony?)

1) Well taken care of!
2) Local Kelowna vehicle!
3) One owner!
4) Purchased @ Harmony!
5) New Battery

SETS OF TIRES

2nd ___ Yes ✓ No

ON RIMS? ___ Yes ✓ No

Front Tires	60 %
Rear Tires	40 %

Front Brakes	80 %
Rear Brakes	70 %

Price $ 12,900

	✓	#
Safety	✓	
Detail	✓	
Online	✓	

CARFAX CANADA

VERIFIED BC VEHICLE HISTORY REPORT

VEHICLE DETAILS:
VIN: 5J6RE4H77AL814383
Year/Make/Model: 2010 HONDA CR-V EXL
Body Style: SPORT UTILITY VEHICLE
Country of Assembly: United States
Cylinders: 4
Fuel Type: Gas

REPORT DETAILS:
Report Number: 27974412
Report Date: 4/15/2020 03:05 PM EST
Report Status: Complete
Reference:

REPORT SUMMARY

Highlights: ONE OWNER™

Accidents / Damage:	Damage records found
Lien Records:	No lien records found
Canadian Registration:	British Columbia (Normal)
Stolen Status:	Not actively declared stolen
U.S. History:	No U.S. history found
Recalls:	No information available
Service History:	18 record(s) found

QUESTIONS?

WE'RE HERE TO HELP.

CALL
1.866.835.8612

EMAIL
SUPPORT@CARFAX.CA

Report Findings in Chronological Order

Below are all records for the vehicle, listed in the order that they occurred.

Date	Location	Data Source	Type of Record	Detail	Odometer
06/19/2010	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
06/19/2010	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	First Owner Reported	
06/25/2011	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
03/01/2012	British Columbia, Canada	Insurance Records	COLLISION		
06/23/2012	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
06/22/2013	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
01/09/2014	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced	72,343 KM
04/28/2014	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced	78,267 KM
06/14/2014	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
06/13/2015	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
[illegible]	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced	105,433 KM

09/16/2015	British Columbia, Canada	Insurance Records	VANDALISM	RIGHT SIDE	
05/31/2016	Kelowna, British Columbia, Canada	Car Craft Automotive	Service Record	Vehicle serviced	129,578 KM
06/11/2016	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
08/26/2016	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced	137,929 KM
09/10/2016	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced	139,265 KM
09/20/2016	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced	140,068 KM
12/28/2016	Kelowna, British Columbia, Canada	Car Craft Automotive	Service Record	Vehicle serviced	149,494 KM
01/23/2017	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced	151,620 KM
05/26/2017	Kelowna, British Columbia, Canada	Car Craft Automotive	Service Record	Vehicle serviced	161,219 KM
09/30/2017	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced	171,443 KM
10/18/2017	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
02/23/2018	Kelowna, British Columbia, Canada	Car Craft Automotive	Service Record	Vehicle serviced	180,675 KM
06/10/2018	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
02/12/2019	Kelowna, British Columbia, Canada	Car Craft Automotive	Service Record	Vehicle serviced	204,321 KM
04/02/2019	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced	206,007 KM
04/25/2019	Kelowna, British Columbia, Canada	Car Craft Automotive	Service Record	Vehicle serviced	206,429 KM
06/03/2019	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
08/09/2019	Vernon, British Columbia, Canada	Great Canadian Oil Change	Service Record	Vehicle serviced	214,381 KM
11/05/2019	Kelowna, British Columbia, Canada	Car Craft Automotive	Service Record	Vehicle serviced	
12/18/2019	Kelowna, British Columbia, Canada	The Great Canadian Oil Change	Service Record	Vehicle serviced	223,316 KM

Accident, Collision and Damage Detail

If the vehicle has had any history of accidents, collisions or damage in either Canada or the U.S., the records are outlined in this section. This report also includes claims and estimates from ICBC.

VIN: 5J6RE4H77AL814383

Police Reported Accidents

Incident Date	Location	Detail
No police reported accidents found		

Accident/Damage Estimates

Accident estimate records are generated by collision estimating facilities from the process of estimating the amount and extent of damage to a vehicle. Estimates in some cases have associated insurance claims.

Incident Date	Location	Estimate Date	Type of Record	Detail	Amount	Odometer
No estimates found						

Insurance Claims

The insurance claims identified in this report do not include any medical pay-outs, damage to other vehicles, damage to property, towing, rental cars, or any other incidental damages.

Incident Date	Location	Type of Claim	Detail	Amount	Odometer
03/01/2012	British Columbia, Canada	COLLISION		$599.28	
09/16/2015	British Columbia, Canada	VANDALISM	RIGHT SIDE	$1,336.87	

Other Damage Records

Record Date	Location	Type of Record	Detail	Odometer
No other damage records found				

Lien Status

This section lists the provinces and territories where we searched for or found a security interest registered against the vehicle (lien). If a lien is found, further details will appear at the end of the report.

Province	Lien
British Columbia	No lien found

CARFAX Canada Canadian Lien Guarantee

Our search results accurately reflect the government records of each personal property and security registry in Canada that is searched at the time the search request is made. If for some reason our search report fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian ($5,000.00), whichever is lower.

Canadian Registration

This section details where in Canada the vehicle is now or has ever been registered, as well as the status (Inspection Required, Normal, Non-repairable, Rebuilt, Salvage, Stolen) of the vehicle in those jurisdictions.

Jurisdiction	Branding	Detail
Alberta	Not found	
British Columbia	**NORMAL**	**This vehicle has been registered as Normal in this jurisdiction.**
Manitoba	Not found	
New Brunswick	Not found	
Newfoundland	Not found	
Nova Scotia	Not found	
Northwest Territories	Not found	
Nunavut	Not found	
Ontario	Not found	
Prince Edward Island	Not found	
Quebec	Not found	
Saskatchewan	Not found	
Yukon Territories	Not found	

Stolen Vehicle Check

This section outlines data from the Canadian Police Information Centre (CPIC), which is operated by the RCMP under the stewardship of National Police Services, on behalf of the Canadian law enforcement community.

Stolen Vehicle Check
Not declared stolen.

Import Records

If the vehicle has been imported, you will find the details below.

Import Records
No vehicle import records found

United States Vehicle History

In addition to information about the vehicle's history in Canada, CARFAX Canada also searches for information about the vehicle's history in the United States. If we discover any events in the U.S., you will find them below. Details about accidents, collisions and damage, or any import records will appear

No U.S. history records found

Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact HONDA or visit Honda's website.

Service History

These are records of service performed on the vehicle. These are the records reported to CARFAX Canada when this report was run – it is possible that service has occurred that is not captured here.

Date	Address	Data Source	Type of Record	Detail	Odometer
01/09/2014	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced Brake fluid flushed/changed Emission system checked Power steering fluid flushed/changed Wiper(s) replaced	72,343 KM
04/28/2014	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced Alignment checked Spark plugs cleaned and gap adjusted	78,267 KM
08/17/2015	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced Front brake pads replaced Brakes replaced	105,433 KM
05/31/2016	Kelowna, British Columbia, Canada	Car Craft Automotive	Service Record	Vehicle serviced Maintenance inspection completed Oil and filter changed	129,578 KM
08/26/2016	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced Electrical system checked	137,929 KM
09/10/2016	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced	139,265 KM
09/20/2016	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced	140,068 KM
12/28/2016	Kelowna, British Columbia, Canada	Car Craft Automotive	Service Record	Vehicle serviced Oil and filter changed Cabin air filter replaced/cleaned	149,494 KM
01/23/2017	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced Airbag replaced	151,620 KM
05/26/2017	Kelowna, British Columbia, Canada	Car Craft Automotive	Service Record	Vehicle serviced A/C system checked A/C refrigerant recharged A/C compressor replaced A/C system flushed A/C compressor serviced	161,219 KM
09/30/2017	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced Key(s) (re) programmed	171,443 KM
02/23/2018	Kelowna, British Columbia, Canada	Car Craft Automotive	Service Record	Vehicle serviced Air filter replaced Oil and filter changed Battery/charging system checked Output shaft seal replaced Transfer case fluid flushed/changed Transfer case rear oil seal replaced	180,675 KM
02/12/2019	Kelowna, British Columbia, Canada	Car Craft Automotive	Service Record	Vehicle serviced Wiper(s) replaced Rear brake caliper(s) replaced Oil and filter changed Brake fluid flushed/changed Brakes checked Brake rotor(s) replaced Tires rotated	204,321 KM
04/02/2019	Kelowna, British Columbia, Canada	Harmony Honda	Service Record	Vehicle serviced Maintenance inspection completed	206,007 KM

Date	Address	Data Source	Record	Detail	Odometer
04/25/2019	Kelowna, British Columbia, Canada	Car Craft Automotive	Service Record	Vehicle serviced Air filter replaced Spark plug(s) replaced Fuel injection system flushed/serviced	206,429 KM
08/09/2019	Vernon, British Columbia, Canada	Great Canadian Oil Change	Service Record	Vehicle serviced Maintenance inspection completed Oil and filter changed	214,381 KM
11/05/2019	Kelowna, British Columbia, Canada	Car Craft Automotive	Service Record	Vehicle serviced Vehicle serviced Maintenance inspection completed	
12/18/2019	Kelowna, British Columbia, Canada	The Great Canadian Oil Change	Service Record	Vehicle serviced Maintenance inspection completed Oil and filter changed	223,316 KM

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts.

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner.
The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim.
In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.
Consumers are encouraged to read ICBC's full statement of limitations at http://apps.icbc.com/registration/vchr/Limitation.html.
ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

CARFAX Canada One Owner™ Badge

The CARFAX Canada One Owner™ badge that appears in this vehicle history report is based on the registration information reported to CARFAX Canada and available for disclosure as of the date and time that this report was generated. The CARFAX Canada One Owner™ badge is available for personal and commercial CARFAX Canada that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI. By using this vehicle history report, you acknowledge and agree that there may be ownership events and/or other information that apply to this vehicle that are not reflected in this report.

CARFAX CANADA © Copyright 2005 - 2020 CARFAX Canada ULC. All rights reserved.

Information on Reports

Conditions of Use

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

Please note CARPROOF recently changed its name to CARFAX Canada!

CUSTOMER #: N/A

201106

INTERNAL

HARMONY ACURA

2552 Enterprise Way Kelowna, BC V1X 7X5
Service Direct: (250) 448-7098
Email: service@harmonyacura.com
GST: 104078324RT0001

HARMONY ACURA
2552 ENTERPISE WAY
KELOWNA, BC V1X 7X5

HOME:
BUS:

CONT:N/A
CELL:

SERVICE ADVISOR: 930 930 930

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
BLUE	10	HONDA CR-V	5J6RE4H77AL814383	996MLN	225119/225119	AU2573

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 30APR20		0.00	CASH	30APR20

R.O. OPENED	READY
14:10 28APR20	16:50 30APR20

OPTIONS: STK:AU2573A DLR:2021 ENG:2.4_Liters
TRN:5_SPEED_AUTOMATIC
1)TRANS-NO:-5_SPEED_AUTOMATIC-OPTIONS:-10345

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
A PERFORM USED CAR SAFETY INSPECTION			
SAFETY PERFORM USED CAR SAFETY INSPECTION			
1093 IUV 1.50		237.00	237.00
1 94109-14000 8 WASHER DRAIN 14MM	0.50	0.50	0.50
5 520AC 5W20 OIL	4.96	4.96	24.80
1 15400-RTA-003 2 OIL FILTER CARTRI	10.92	10.92	10.92
PARTS: 36.22 LABOR: 237.00 OTHER:	0.00	TOTAL LINE A:	273.22
225119 1.50			
**********			
B PERFORM ACURA RECALL			
RECALL PERFORM ACURA RECALL			
1093 IUV 0.00		0.00	0.00
**********			
C** REPLACE PASSENGER FRONT DOOR LOCK ACTUATOR			
GEN PASSENGER DOOR LOCK ACTUATOR			
1093 IUV 1.30		182.00	182.00
1 72110-SWA-D01 LATCH ASS	128.51	128.51	128.51
PARTS: 128.51 LABOR: 182.00 OTHER:	0.00	TOTAL LINE C:	310.51
225119 1.30			
**********			
D** REPLACE WIPER BLADES			
WIPER REPLACE WIPER BLADES			
1093 IUV 0.00		0.00	0.00
1 76630-SWA-A01 BLADE	49.97	49.97	49.97
1 76620-SWA-A01 BLADE	80.29	80.29	80.29
1 76632-S2K-004 2 BLADE RUBBER	9.80	9.80	9.80
PARTS: 140.06 LABOR: 0.00 OTHER:	0.00	TOTAL LINE D:	140.06
**********			
E** REPLACE BATTERY			
BATT REPLACE BATTERY			
1093 IUV 0.20		42.00	42.00
BATT BATTERY RECYCLING FEE		5.00	5.00
1 31500-CCA-H500R BATTERY	171.00	169.99	169.99
PARTS: 169.99 LABOR: 42.00 OTHER:	5.00	TOTAL LINE E:	216.99

TEXTING DISCLAIMER: Harmony Acura has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

I understand that Acura, its affiliates, dealers and service providers collect, use and disclose my personal information for the purposes of (i) completing my purchase, finance or lease transaction; (ii) maintaining my warranty and customer service records; (iii) conducting customer service campaigns; ((iv) providing me with marketing information; and (v) for legal and other business purposes. I consent to Acura, its affiliates, dealers and service providers contacting me by telephone or sending commercial electronic messages to me, including email and text messages. I can contact Acura at 1-888-922-8729 or 180 Honda Boulevard, Markham, Ontario L6C 0H9, and my dealer if I no longer consent to these uses and to update or correct my personal information.

x_____
CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
TAX	
PLEASE PAY THIS AMOUNT	

PARTS & SERVICE HOURS: MONDAY - FRIDAY 7:30 AM - 5:30 PM SATURDAY 8:00 AM - 4:00 PM

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2CE - IMAGING

INTERNAL COPY

CUSTOMER #: N/A

201106

INTERNAL

HARMONY ACURA

HARMONY ACURA
2552 ENTERPISE WAY
KELOWNA, BC V1X 7X5

PAGE 2

2552 Enterprise Way Kelowna, BC V1X 7X5
Service Direct: (250) 448-7098
Email: service@harmonyacura.com
GST: 104078324RT0001

HOME:
BUS:

CONT:N/A
CELL:

SERVICE ADVISOR: 930 930 930

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
BLUE	10	HONDA CR-V	5J6RE4H77AL814383	996MLN	225119/225119	AU2573

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 30APR20		0.00	CASH	30APR20

R.O. OPENED	READY	OPTIONS: STK:AU2573A DLR:2021 ENG:2.4_Liters TRN:5_SPEED_AUTOMATIC 1)TRANS-NO:-5_SPEED_AUTOMATIC-OPTIONS:-10345
14:10 28APR20	16:50 30APR20	

LINE OPCODE TECH TYPE HOURS		LIST	NET	TOTAL
225119 0.20				
**********				
F** SUB SYMBOL 2 CARS 4CYL TRUCKS $134.95				
91ACZ229 SUB SYMBOL 2 CARS 4CYL TRUCKS $134.95				
1093 IUV 0.30			79.14	79.14
1 17220-REZ-A00 ELEMENT ASSY AIR/		28.71	28.71	28.71
1 80292-SDA-407 2 ELEMENT FILTER		32.59	32.59	32.59
PARTS: 61.30 LABOR: 79.14 OTHER: 0.00 TOTAL LINE F:				140.44
225119 0.30 REPLACE ENGINE AIR FILTER, CABIN AIR FILTER, AND INSPECT DRIVE BELTS				
**********				
G** REPLACE TRANSFER CASE O - RING				
GEN TRANSFER CASE O RINGS				
1093 IUV 1.40			196.00	196.00
1 91301-PH8-005 O-RING		21.89	21.89	21.89
1 91304-RKJ-003 O-RING		15.84	15.84	15.84
PARTS: 37.73 LABOR: 196.00 OTHER: 0.00 TOTAL LINE G:				233.73
225119 1.40				
**********				

EST: 363.14 30APR20 15:20 SA: 930
CONTACT: .

COST/SALE/COMP TOT: 48278 131495 0

TEXTING DISCLAIMER: Harmony Acura has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

I understand that Acura, its affiliates, dealers and service providers collect, use and disclose my personal information for the purposes of (i) completing my purchase, finance or lease transaction; (ii) maintaining my warranty and customer service records; (iii) conducting customer service campaigns; ((iv) providing me with marketing information; and (v) for legal and other business purposes. I consent to Acura, its affiliates, dealers and service providers contacting me by telephone or sending commercial electronic messages to me, including email and text messages. I can contact Acura at 1-888-922-8729 or 180 Honda Boulevard, Markham, Ontario L6C 0H9, and my dealer if I no longer consent to these uses and to update or correct my personal information.

x_____
CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOUR AMOUNT	736.14
PARTS AMOUNT	573.81
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	5.00
TOTAL CHARGES	1314.95
LESS INSURANCE	0.00
TAX	0.00
PLEASE PAY THIS AMOUNT	1314.95

PARTS & SERVICE HOURS: MONDAY - FRIDAY 7:30 AM - 5:30 PM SATURDAY 8:00 AM - 4:00 PM

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2CE - IMAGING

INTERNAL COPY

Acura Multi-Point Vehicle Inspection Checklist

ACURA TIRE SOURCE

ACURA ADVANCE.

HARMONY ACURA

R/O NUMBER 201106	NEXT SERVICE DUE
CUSTOMER NAME VEHICLE INVENTORY	ODOMETER 225119
SERVICE ADVISOR Mykeal Antaloczy	TECHNICIAN Karlin Gamache

Satisfactory | May Require Further Attention | Requires Immediate Attention

Interior/Exterior	✓		
Headlights (check high and low beams)	✓		
Taillights	✓		
Turn signals	✓		
Brake lights	✓		
Hazard warning lights	✓		
Interior light	✓		
Windshield washer spray, wiper operation and wiper blades	✓		
Windshield condition	✓		
Parking brake	✓		
Horn operation	✓		
Clutch operation (if applicable)			

Battery Performance (see printout)		
Good	✓	
Replace		mm/dd/yyyy

Under Hood			
Engine oil level	✓		
Coolant level	✓		
Power steering fluid level	✓		
Brake fluid level	✓		
Windshield washer fluid level	✓		
Transmission fluid level	✓		
External drive belts and radiator hoses	✓		
Air/Cabin/Dust & Pollen Filter	✓		
Under Vehicle			
Brake lines/Hoses/Parking brake cable	✓		
Hydraulic clutch reservoir fluid (M/T vehicles)			
Shock absorbers/Struts/Suspension	✓		
Exhaust system	✓		
Engine oil and/or fluid leaks	✓		
Drive shaft/Constant velocity boots and bands	✓		
Steering Gearbox Components	✓		

Genuine Floor Mats		
Genuine floor mats installed	✓	
Anchored properly and only 1 mat at driver's position	✓	

PAM2269E

*NOTE: Brake fluid NOT filled - fluid level indicates pad wear

Tire Condition	6/32 or more	4/32 to 5/32	3/32 or less
Left Front			Right Front
✓	Wear pattern	Wear pattern	✓
✓	Tire tread 40 32nds	Tire tread 40 32nds	✓
Left Rear			Right Rear
✓	Wear pattern	Wear pattern	✓
✓	Tire tread 60 32nds	Tire tread 60 32nds	✓
Spare			
✓	Wear pattern	Front tire inflation set to 33 psi	
✓	Tire tread ____ 32nds	Rear tire inflation set to No psi	
Rotation/Alignment/Replacement suggested?		Yes ☑ No ☐	
Seasonal tire changeover suggested?		Yes ☑ No ☐	

Brake Inspection Not Performed At This Service ☑

Brake Condition	5 mm or more	3 - 4 mm	2 mm or less
Left Front			Right Front
✓	____ mm 80 %	____ mm 80 %	✓
Left Rear			Right Rear
✓	____ mm 70 %	____ mm 70 %	✓

Please Indicate Areas of External Damage or Wear



Maintenance Indicator Light Reset ***YES*** ☑

Any Outstanding Recalls / PUD ***YES*** ☐ ***NO*** ☑

Comments