HARMONY Honda

THE HARMONY GUARANTEE - WE GUARANTEE YOU'LL LIKE YOUR PRE-OWNED VEHICLE

1. No Documentation Fees or Hidden Charges
2. 120 Point Inspection on Every Pre-Owned Vehicle
3. 30 Day 2500 KM Exchange Policy
4. Complete Vehicle Detail
5. CarProof Vehicle History Report
6. Full Tank of Gas

2009 HYUNDAI SANTA FE

STOCK #: 19103A

VIN NUMBER: 5NMSG13DX9H313496

COLOUR: BLACK

ODOMETER: 191384

SEATS: 5

ENGINE: 2.7L/6CYL

TRANSMISSION: MANUAL



WHAT MAKES THIS VEHICLE UNIQUE?

- BC VEHICLE !!
- NON SMOKER !!
- WINTERS AT 60% !!
- FORWARD DRIVE !!

For more information on this vehicle visit www.harmonyhonda.com

PRICE $9,500

2550 Enterprise Way
Kelowna, BC
V1X 7X5
PH: 250-860-6500

Monday - Thursday 8am - 7pm
Friday - Saturday 8am - 6pm
Closed Sunday
www.harmonyhonda.com

HARMONY Honda

USED CAR CHECK-IN SHEET

SALES REP: Jessica

YEAR	MAKE	TRIM	ENGINE DISP.	# CYL	ENG HP	MILEAGE	STOCK #
2009	Hyundai	GL				191384	19103A
	MODEL Santafe	BODY SUV	2.7	6	185		

VIN	TRANS.	COLOUR - EXT.	COLOUR - INT.
5NMSG13DX9H319496	Manual	Black	Grey

EQUIPMENT

- ✓ AM/FM Stereo
- ✓ AM/FM Stereo w/CD
- X DVD System (RES)
- X Bluetooth
- ✓ Air Conditioning
- ✓ Cruise Control
- ✓ Tilt Steering
- X Leather Interior
- ✓ Power Windows/Mirrors
- ✓ Power Door Locks
- X Power Trunk
- ✓ Floor Mats
- ___ Alloy Wheels
- ✓ Remote Keyless Entry
- X Power Driver's Seat
- X Dual Power Seats
- X Cooled Seats / Heated Seats
- X Push Button Start
- X Navigation System
- X Backup Camera
- X Blind Spot Monitors
- X Rear Spoiler
- X Sunroof / Panoramic Roof
- ___ Fog Lights
- X Tire Pressure Monitoring System (TPMS)
- ✓ Driver's Side Airbags (SIR)
- ✓ Dual Airbags (SIR)
- ✓ Side Airbags
- ✓ Side Curtain Airbags
- ✓ Anti-Lock Brakes / VSA
- ✓ Anti-Theft Device
- ___ Drive Train - 4WD / AWD / (FWD) / RWD / 4X4
- 5 Seats (# of)
- ___ Accessories
- ___ Other
- ___ Other

X Active Safety Radars / Driver Assist Technologies: X

FACTORY WARRANTY EXPIRES: X DATE OR X MILEAGE

DECLARATIONS

Any Accidents/Damage	✓ Yes	___ No
Damage Over $2000	___ Yes	✓ No
Ex-Lease	___ Yes	✓ No
Ex-Rental	___ Yes	✓ No
Out of Province	___ Yes	✓ No
If Yes, Province:		

OTHER INFORMATION

Extra Keys	✓ Yes	___ No
Extra Remotes	✓ Yes	___ No
Owner's Manual	✓ Yes	___ No
Radio Code		
Key Code		

VEHICLE HISTORY

What makes this vehicle unique?

(I.E.: Traded in on? # of owners? Purpose of vehicle use? Previous customer info? No accidents? Bought & serviced at Harmony?)

1) BC vehicle
2) non smoker
3) Traded in on a new Odyssey
4)
5) Winters 60%

SETS OF TIRES

2nd ✓ Yes ___ No

ON RIMS? ✓ Yes ___ No

Front Tires	80	%	Front Brakes	70	%
Rear Tires	80	%	Rear Brakes	70	%

Price $ 9,500

	✓	#
Safety	✓	
Detail	✓	
Online	✓	

QF10c Rev.F
Sep-17

CARFAX CANADA

CLAIMS BC VEHICLE HISTORY REPORT

VEHICLE DETAILS:
VIN: 5NMSG13DX9H313496
Year/Make/Model: 2009 HYUNDAI SANTA FE GLS
Body Style: SPORT UTILITY VEHICLE
Country of Assembly: United States
Cylinders: 6
Fuel Type: Gas

REPORT DETAILS:
Report Number: 26441734
Report Date: 11/22/2019 02:28 PM EST
Report Status: Complete

REPORT SUMMARY

Highlights: ONE OWNER

Accidents / Damage:	Damage records found
Canadian Registration:	British Columbia (Normal)
Stolen Status:	Not actively declared stolen
U.S. History:	No U.S. history found
Recalls:	Unable to check for recall information
Service History:	1 record(s) found

QUESTIONS?
WE'RE HERE TO HELP.
CALL
1.866.835.8612
EMAIL
SUPPORT@CARFAX.CA

Report Findings in Chronological Order

Below are all records for the vehicle, listed in the order that they occurred.

Date	Location	Data Source	Type of Record	Detail	Odometer
01/23/2010	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
01/23/2010	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	First Owner Reported	
10/01/2010	British Columbia, Canada	Insurance Records	Estimate	LEFT REAR SIDE	
11/15/2010	Canada	Hyundai	Service Record		14,143 KM
01/22/2011	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
01/21/2012	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
01/26/2013	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
01/25/2014	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
11/09/2014	British Columbia, Canada	Insurance Records	Glass Record	$996.44	
01/24/2015	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
01/23/2016	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
01/22/2017	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
01/20/2018	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	

Date	Location	Data Source	Type of Record	Detail	Odometer
01/20/2019	British Columbia, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
09/03/2019	Kelowna, British Columbia, Canada	The Great Canadian Oil Change	Service Record	Vehicle serviced	188,435 KM

Accident, Collision and Damage Detail

If the vehicle has had any history of accidents, collisions or damage in either Canada or the U.S., the records are outlined in this section. This report also includes claims and estimates from ICBC.

VIN: 5NMSG13DX9H313496

Police Reported Accidents

Incident Date	Location	Detail
No police reported accidents found		

Accident/Damage Estimates

Accident estimate records are generated by collision estimating facilities from the process of estimating the amount and extent of damage to a vehicle. Estimates in some cases have associated insurance claims.

Incident Date	Location	Estimate Date	Type of Record	Detail	Amount	Odometer
10/01/2010	British Columbia, Canada		Estimate	LEFT REAR SIDE	$150.26	

Insurance Claims

The insurance claims identified in this report do not include any medical pay-outs, damage to other vehicles, damage to property, towing, rental cars, or any other incidental damages.

Incident Date	Location	Type of Claim	Detail	Amount	Odometer
No claims found					

Other Damage Records

Record Date	Location	Type of Record	Detail	Odometer
11/09/2014	British Columbia, Canada	Glass Record	$996.44	

Canadian Registration

This section details where in Canada the vehicle is now or has ever been registered, as well as the status (Inspection Required, Normal, Non-repairable, Rebuilt, Salvage, Stolen) of the vehicle in those jurisdictions.

Jurisdiction	Branding	Detail
Alberta	Not found	
British Columbia	**NORMAL**	**This vehicle has been registered as Normal in this jurisdiction.**
Manitoba	Not found	
New Brunswick	Not found	
Newfoundland	Not found	
Nova Scotia	Not found	
Northwest Territories	Not found	
Nunavut	Not found	
Ontario	Not found	
Prince Edward Island	Not found	
Quebec	Not found	
Saskatchewan	Not found	
Yukon Territories	Not found	

Stolen Vehicle Check

This section outlines data from the Canadian Police Information Centre (CPIC), which is operated by the RCMP under the stewardship of National Police Services, on behalf of the Canadian law enforcement community.

Stolen Vehicle Check

Not declared stolen.

Import Records

If the vehicle has been imported, you will find the details below.

Import Records

No vehicle import records found

United States Vehicle History

In addition to information about the vehicle's history in Canada, CARFAX Canada also searches for information about the vehicle's history in the United States. If we discover any events in the U.S., you will find them below. Details about accidents, collisions and damage, or any import records will appear in the preceding sections of your report.

U.S. History Records

No U.S. history records found

Recalls

We are unable to check for recall information on this vehicle. Please visit HYUNDAI's website for the most current recall information on this, or any, HYUNDAI vehicle https://recall.hyundaicanada.com/.

Service History

These are records of service performed on the vehicle. These are the records reported to CARFAX Canada when this report was run – it is possible that service has occurred that is not captured here.

Date	Address	Data Source	Type of Record	Detail	Odometer
09/03/2019	Kelowna, British Columbia, Canada	The Great Canadian Oil Change	Service Record	Vehicle serviced Maintenance inspection completed Oil and filter changed	188,435 KM

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts.

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner.
The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim.
In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.
Consumers are encouraged to read ICBC's full statement of limitations at http://apps.icbc.com/registration/vchr/Limitation.html.
ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

CARFAX Canada One Owner™ Badge

The CARFAX Canada One Owner™ badge that appears in this vehicle history report is based on the registration information reported to CARFAX Canada and available for disclosure as of the date and time that this report was generated. The CARFAX Canada One Owner™ badge is available for personal and commercial CARFAX Canada that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI. By using this vehicle history report, you acknowledge and agree that there may be ownership events and/or other information that apply to this vehicle that are not reflected in this report.

© Copyright 2005 - 2019 CARFAX Canada ULC. All rights reserved.

Information on Reports

Conditions of Use

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained

within a report, including the accuracy thereof or any delay or failure to provide a report or any information. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

Please note CARPROOF recently changed its name to CARFAX Canada!

HARMONY Honda

2550 Enterprise Way, Kelowna BC, V1X-7X5
Phone: 250-860–6530 • Fax: 250-860-6562
Toll Free: 1-877-914-6632 • service@harmonyhonda.com
www.harmonyhonda.com • GST: 10144 7027 RT0001

Promised: 12/03/2019 5:30:00 PM
PO
Fleet
Tag#:

REPRINT

Cashiered Date: 12/19/2019 9:35:24 AM

* Service Invoice Internal Copy *

SO #: 331510

Customer No: 1

HARMONY HONDA HARMONY AUTO SALE
2550 ENTERPRISE WAY
KELOWNA, BC V1X 7X5

Home: (250) 860-6500 **Bus:** (250) 860-6500
Cell: **Today:**(250) 860-6500
Email: reception@harmonyhonda.com

Advisor: Larry B **Invoice Date:** 12/19/2019 **Term:** CHARGE

License No	Odometer In	Odometer Out	Delivery Date	Stock No
	191389	191391		19103A

Year	Make	Model	Model No	Colour
2009	HYUNDAI	SANTA FE	SG1	BLACK

Vehicle ID No 5NMSG13DX9H313496 **Selling Dealer** **SO Date** 12/03/2019 **InServ Date** **Location**
Engine Size 2.7L DOHC CVVT V6 engine **Fleet#**

	Request/Concern		Type	CSR	Amount
1	BLADES	WIPER BLADES			
	BLADES	WIPER BLADES	I	922	0.00

QTY	OH					RETAIL	Price	Ext
1	0	SP-OR	NPN	WIPER BLADE	I	18.00	18.00	18.00
1	0	SP-OR	NPN	WIPER BLADE	I	17.00	17.00	17.00
1	0	SP-OR	NPN	BLADE	I	28.08	28.08	28.08

Name 1093

Request Total 63.08

	Added Operation		Type	CSR	Amount
2	ALIGN	4 WHEEL ALIGNMENT $92.88			
	ALIGN	4 WHEEL ALIGNMENT $92.88	I	922	94.00

Name 1093

Cause: 4 WHEEL ALIGNMENT
Correction: PEFORMED 4 WHEEL ALIGNMENT

Request Total 94.00

	Added Operation		Type	CSR	Amount
3	09	REPLACE LEFT & RIGHT SUN VISORS			
	09	REPLACE LEFT & RIGHT SUN VISORS	I	922	56.00

QTY	OH					RETAIL	Price	Ext
1	0	SP-OR	NPN	LEFT & RIGHT VISOR	I	383.24	383.24	383.24

Name 1093

Cause: .
Correction: .

Request Total 439.24

	Added Operation		Type	CSR	Amount
4	09	REPLACE STEERING WHEEL			

I understand that Honda, its affiliates, dealers and service providers collect, use and disclose my personal information for the purposes of (i) completing my purchase, finance or lease transaction; (ii) maintaining my warranty and customer service records; (iii) conducting customer service campaigns; (iv) providing me with marketing information; and (v) for legal and other business purposes. I consent to Honda, its affiliates, dealers and service providers contacting me by telephone or sending commercial electronic messages to me, including email and text messages. I can contact Honda at 1-888-946-6329 or 180 Honda Boulevard, Markham, Ontario, L6C 0H9, and my dealer if I no longer consent of these uses and to update or correct my personal information.

X _____
CUSTOMER SIGNATURE

PARTS AND SERVICE HOURS
MONDAY-FRIDAY
7:30AM-5:30PM
SATURDAY
8:00AM–4:00PM

Book your service at harmonyhonda.com and trust your ride to us.

Thank you - Jeff Hautamaki
Fixed Operations Manager

HARMONY Honda

2550 Enterprise Way, Kelowna BC, V1X-7X5
Phone: 250-860–6530 • Fax: 250-860-6562
Toll Free: 1-877-914-6632 • service@harmonyhonda.com
www.harmonyhonda.com • GST: 10144 7027 RT0001

Promised: 12/03/2019 5:30:00 PM
PO
Fleet
Tag#:

REPRINT

Cashiered Date: 12/19/2019 9:35:24 AM

* Service Invoice Internal Copy *

SO #: 331510

Customer No: 1

HARMONY HONDA HARMONY AUTO SALE
2550 ENTERPRISE WAY
KELOWNA, BC V1X 7X5

Home: (250) 860-6500 **Bus:** (250) 860-6500
Cell: **Today:**(250) 860-6500
Email: reception@harmonyhonda.com

Advisor: Larry B **Invoice Date:** 12/19/2019 **Term:** CHARGE

License No	Odometer In	Odometer Out	Delivery Date	Stock No
	191389	191391		19103A

Year	Make	Model	Model No	Colour
2009	HYUNDAI	SANTA FE	SG1	BLACK

Vehicle ID No	Selling Dealer	SO Date	InServ Date	Location
5NMSG13DX9H313496		12/03/2019		

Engine Size 2.7L DOHC CVVT V6 engine **Fleet#**

Request/Concern				Type	CSR	Amount
09			REPLACE STEERING WHEEL	I	922	112.00

QTY	OH					RETAIL	Price	Ext
1	0	SP-OR	NPN	STEERING WHEEL	I	686.88	686.00	686.00

Name 1093

Cause: .
Correction: .

Request Total 798.00

Added Operation

5	09	RECHARGE A/C
	09	RECHARGE A/C

QTY	OH					RETAIL	Price	Ext
1	42	BULK	R134A	R134A RECHARGE	I	36.00	36.00	36.00

Name 1093

Cause: .
Correction: .

Request Total 386.00

Added Operation

6	09	REPLACE RIGHT LOWER CONTROL ARM
	09	REPLACE RIGHT LOWER CONTROL ARM

QTY	OH					RETAIL	Price	Ext
1	0	SP-OR	NPN	BALL JOINT	I	10.40	6.24	6.24

Name 1093

Cause: .
Correction: .

Request Total 61.74

Added Operation

7	09	REPLACE CENTRE CONSOLE /ON DASH

I understand that Honda, its affiliates, dealers and service providers collect, use and disclose my personal information for the purposes of (i) completing my purchase, finance or lease transaction; (ii) maintaining my warranty and customer service records; (iii) conducting customer service campaigns; (iv) providing me with marketing information; and (v) for legal and other business purposes. I consent to Honda, its affiliates, dealers and service providers contacting me by telephone or sending commercial electronic messages to me, including email and text messages. I can contact Honda at 1-888-946-6329 or 180 Honda Boulevard, Markham, Ontario, L6C 0H9, and my dealer if I no longer consent of these uses and to update or correct my personal information.

X _____
CUSTOMER SIGNATURE

PARTS AND SERVICE HOURS
MONDAY-FRIDAY
7:30AM-5:30PM
SATURDAY
8:00AM–4:00PM

Book your service at harmonyhonda.com and trust your ride to us.

Thank you - Jeff Hautamaki
Fixed Operations Manager

HARMONY Honda

2550 Enterprise Way, Kelowna BC, V1X-7X5
Phone: 250-860–6530 • Fax: 250-860-6562
Toll Free: 1-877-914-6632 • service@harmonyhonda.com
www.harmonyhonda.com • GST: 10144 7027 RT0001

Promised: 12/03/2019 5:30:00 PM
PO
Fleet
Tag#:

REPRINT

Cashiered Date: 12/19/2019 9:35:24 AM

* Service Invoice Internal Copy *

SO #: 331510

Customer No: 1

HARMONY HONDA HARMONY AUTO SALE
2550 ENTERPRISE WAY
KELOWNA, BC V1X 7X5

Home: (250) 860-6500 **Bus:** (250) 860-6500
Cell: **Today:**(250) 860-6500
Email: reception@harmonyhonda.com

Advisor: Larry B **Invoice Date:** 12/19/2019 **Term:** CHARGE

License No	Odometer In	Odometer Out	Delivery Date	Stock No
	191389	191391		19103A

Year	Make	Model	Model No	Colour
2009	HYUNDAI	SANTA FE	SG1	BLACK

Vehicle ID No	Selling Dealer	SO Date	InServ Date	Location
5NMSG13DX9H313496		12/03/2019		

Engine Size 2.7L DOHC CVVT V6 engine **Fleet#**

Request/Concern			Type	CSR	Amount
09		REPLACE CENTRE CONSOLE /ON DASH	I	922	70.00

QTY	OH				Type	RETAIL	Price	Ext
1	0	SP-OR	NPN	Ashtray 334052 K.H	I	0.00	195.00	195.00

Name 1093

Cause: .

Correction: .

Request Total 265.00

Added Operation

8	MPI-HONDA	Honda Canada Multi-Point Vehicle Inspection Checklist			
	HI	COMPLIMENTARY HONDA VEHICLE MULTI-POINT INSPECTION	I	922	0.00

Name 1093

Cause: MULTI POINT INSPECTION

Correction: PERFORMED HONDA FACTORY MULTI-POINT INSPECTION, DETAILS INCLUDED ON PRINT OUT

Request Total 0.00

	LABOUR SALE	PARTS SALE	OIL/GAS	MISC.	SUPPLIES	SUBLET /TOW	ENV FEE	WARR DEDUCTIBLE	GST	PST	TOTAL
C	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
W	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
I	737.50	1,369.56	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	2,107.06
TOTALS	737.50	1,369.56	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	2,107.06

INTERNAL DETAILS

Account	Description	Type	Control #	Amount	Comments
138	USED VEHICLE INVENTORY	U	19103A	2,107.06	19103A - 2009 HYUNDAI SANTA FE GL

I understand that Honda, its affiliates, dealers and service providers collect, use and disclose my personal information for the purposes of (i) completing my purchase, finance or lease transaction; (ii) maintaining my warranty and customer service records; (iii) conducting customer service campaigns; (iv) providing me with marketing information; and (v) for legal and other business purposes. I consent to Honda, its affiliates, dealers and service providers contacting me by telephone or sending commercial electronic messages to me, including email and text messages. I can contact Honda at 1-888-946-6329 or 180 Honda Boulevard, Markham, Ontario, L6C 0H9, and my dealer if I no longer consent of these uses and to update or correct my personal information.

X _____
CUSTOMER SIGNATURE

PARTS AND SERVICE HOURS
MONDAY-FRIDAY
7:30AM-5:30PM
SATURDAY
8:00AM–4:00PM

Book your service at harmonyhonda.com and trust your ride to us.

Thank you - Jeff Hautamaki
Fixed Operations Manager

Honda Multi-Point Vehicle Inspection Checklist

HONDA GENUINE PARTS & SERVICE

BOOK YOUR NEXT SERVICE APPOINTMENT ONLINE.

R/O Number: 331510

Customer Name: HARMONY HONDA

Odometer: HARMONY AUTO 191389 SALES LTD

Next Service Due: A [X] B [ ]

Advisor: Larry Bossi

Technician: Karlin Gamache

Satisfactory | May Require Further Attention | Requires Immediate Attention

Interior/Exterior				
Headlights (check high and low beams)	X			
Taillights	X			
Turn signals	X			
Brake lights	X			
Hazard warning lights	X			
Interior light	X			
Windshield washer spray, wiper operation and wiper blades	X			
Windshield condition	X			
Parking brake	X			
Horn operation	X			
Clutch operation (if applicable)	X			

Battery Performance (see printout)		Date of Manufacture
Good	X	
Replace		

Under Hood			
Engine oil level	X		
Coolant level	X		
Power steering fluid level	X		
Brake fluid level	X		
Windshield washer fluid level	X		
Transmission fluid level	X		
External drive belts and radiator hoses	X		
Air/Cabin/Dust & Pollen Filter	X		
Under Vehicle			
Brake lines/Hoses/Parking brake cable	X		
Hydraulic clutch reservoir fluid (M/T vehicles)	X		
Shock absorbers/Struts/Suspension	X		
Exhaust system	X		
Engine oil and/or fluid leaks	X		
Drive shaft/Constant velocity boots and bands	X		
Steering Gearbox Components	X		

Genuine Floor Mats		
Genuine floor mats installed	X	
Anchored properly and only 1 mat at driver's position	X	

**NOTE: Brake fluid NOT filled - fluid level indicates pad wear*

Tire Condition — 6/32 or more | 4/32 to 5/32 | 3/32 or less

Left Front		Right Front
Wear pattern	Wear pattern	
Tire tread 80 32nds	Tire tread 80 32nds	
Left Rear		**Right Rear**
Wear pattern	Wear pattern	
Tire tread 80 32nds	Tire tread 80 32nds	
Spare		
Wear pattern	Front tire inflation set to 33 psi	
Tire tread ____ 32nds	Rear tire inflation set to 33 psi	

Rotation/Alignment/Replacement suggested? Yes [ ] No [ ]

Seasonal tire changeover suggested? Yes [ ] No [ ]

Brake Inspection Not Performed At This Service [ ]

Brake Condition — 5 mm or more | 3 - 4 mm | 2 mm or less

Left Front		Right Front
____ mm 80 %	____ mm 80 %	
Left Rear		**Right Rear**
____ mm 80 %	____ mm 80 %	

Please Indicate Areas of External Damage or Wear



Maintenance Indicator Light Reset YES [X]

Any Outstanding Recalls / PUD YES [ ] NO [X]

Comments

Lowest Price Guarantee on Tires* | **Lifetime Brake Pad Guarantee*** | **Lowest Price Guarantee on 0W-20 Oil Changes***

** Some conditions and restrictions apply. Ask your Honda Service Advisor for complete details.*