HARMONY Honda

THE HARMONY GUARANTEE - WE GUARANTEE YOU'LL LIKE YOUR PRE-OWNED VEHICLE

1. No Documentation Fees or Hidden Charges
2. 120 Point Inspection on Every Pre-Owned Vehicle
3. 30 Day 2500 KM Exchange Policy
4. Complete Vehicle Detail
5. CarProof Vehicle History Report
6. Full Tank of Gas

2008 HONDA CRV EXL

STOCK #: U8285

VIN NUMBER: 5J6RE48758L805420

COLOUR: GREEN

ODOMETER: 146,216

SEATS: 5

ENGINE: 2.5L/4CYL

TRANSMISSION: AUTO

Front Brake Life: 70 %

Rear Brake Life: 100 %

Front Tire Tread Life: 95 %

Rear Tire Tread Life: 90 %

WHAT MAKES THIS VEHICLE UNIQUE?

GREAT CONDITION!!!

LOW KMS!!!

LOADED!!!

For more information on this vehicle visit **www.harmonyhonda.com**

PRICE $23,900

2550 Enterprise Way
Kelowna, BC
V1X 7X5
PH: **250-860-6500**

Monday - Thursday 8am - 7pm
Friday - Saturday 8am - 6pm
Closed Sunday
www.harmonyhonda.com

HARMONY Honda

USED CAR CHECK-IN SHEET

SALES REP: Randy S

YEAR	MAKE	TRIM	ENGINE DISP.	# CYL.	ENG HP	MILEAGE	STOCK #
2008	Honda	EXL	2.5	4	180	146216	U8285
	MODEL CRV.	BODY SUV					

VIN	TRANS.	COLOUR - EXT.	COLOUR - INT.
5J6RE48758L805420	AUTO	Green	BLACK

EQUIPMENT

- ___ AM/FM Stereo
- ✓ AM/FM Stereo w/CD
- ___ DVD System (RES)
- ___ Bluetooth
- ✓ Air Conditioning
- ✓ Cruise Control
- ✓ Tilt Steering
- ✓ Leather Interior
- ✓ Power Windows/Mirrors
- ✓ Power Door Locks
- ___ Power Trunk
- ✓ Floor Mats
- ✓ Alloy Wheels
- ✓ Remote Keyless Entry
- ✓ Power Driver's Seat
- ___ Dual Power Seats
- ___ Cooled Seats / Heated Seats
- ___ Push Button Start
- ___ Navigation System
- ___ Backup Camera
- ___ Blind Spot Monitors
- ___ Rear Spoiler
- ✓ Sunroof / Panoramic Roof
- ___ Fog Lights
- ✓ Tire Pressure Monitoring System (TPMS)
- ___ Driver's Side Airbags (SIR)
- ✓ Dual Airbags (SIR)
- ✓ Side Airbags
- ✓ Side Curtain Airbags
- ✓ Anti-Lock Brakes / VSA
- ___ Anti-Theft Device
- ___ Drive Train - 4WD / AWD / FWD / RWD / 4X4
- ___ Seats (# of) _____
- ___ Accessories _____
- ___ Other _____
- ___ Other _____

___ Active Safety Radars / Driver Assist Technologies: _____

FACTORY WARRANTY EXPIRES: _____ DATE OR _____ MILEAGE

DECLARATIONS

Any Accidents/Damage	✓ Yes	___ No
Damage Over $2000	✓ Yes	___ No
Ex-Lease	___ Yes	✓ No
Ex-Rental	___ Yes	___ No
Out of Province	___ Yes	✓ No
If Yes, Province:		

OTHER INFORMATION

Extra Keys	✓ Yes	___ No
Extra Remotes	ONE ✓ Yes	___ No
Owner's Manual	___ Yes	___ No
Radio Code		
Key Code		

VEHICLE HISTORY

What makes this vehicle unique?

(I.E.: Traded in on? # of owners? Purpose of vehicle use? Previous customer info? No accidents? Bought & serviced at Harmony?)

1) GREAT CONDITION
2) LOW KMS
3) LOADED
4)
5)

SETS OF TIRES

2nd ___ Yes ___ No

ON RIMS? ___ Yes ___ No

Front Tires	95 %
Rear Tires	90 %

Front Brakes	70 %
Rear Brakes	100 %

✓ #

Price $ 23,900

	✓	#
Safety	✓	
Detail		
Online		

QF10c Rev.F
Sep-17

CARFAX

Vehicle History Report (BC) #: 41720266
Report Date: September 13, 2022 | 06:24 PM EST
Report Status: Complete

2008 HONDA CR-V EXL

Sport utility vehicle | 4 Cylinders | Gas
5J6RE48758L805420
Country of Assembly: United States
Last Reported Odometer: 114,315 KM

Accident/Damage Records Found

Last Registered In:
British Columbia (Normal)

2 Service Records Found

No U.S. History Found

No Open Recalls Found

Not Actively Declared Stolen

No Import Record Found

Questions? We're here to help.

Visit us at **support.carfax.ca**

This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of September 13, 2022 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

5J6RE48758L805420

Vehicle History Report (BC)

Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2009 Apr 1	**British Columbia, Canada**	
	Claim: VANDALISM	$428.10
2011 Feb 8	**British Columbia, Canada**	
	Estimate: RIGHT FRONT CORNER | Estimate Date: n/a	$862.25
	Claim: COLLISION RIGHT FRONT CORNER	$769.87
2011 Oct 4	**British Columbia, Canada**	
	Estimate: RIGHT SIDE | Estimate Date: n/a	$3,238.82
	Claim: COLLISION RIGHT SIDE	$3,238.82
2016 Nov 14	**British Columbia, Canada**	
	Estimate: LEFT FRONT CORNER | Estimate Date: n/a	$1,701.53
	Claim: COLLISION LEFT FRONT CORNER	$1,570.29
2018 Dec 22	**British Columbia, Canada**	
	Estimate: COLLISION | Estimate Date: n/a	$0.00
	Claim: COLLISION	$0.00

Registration

This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*

Service Records

DATE	ODOMETER	SOURCE	DETAILS
2016 Aug 9	113,266 KM	Mobil 1 Lube King Oil Change Coquitlam, British Columbia, Canada	**Vehicle serviced** • Vehicle washed/detailed

5J6RE48758L805420

DATE	ODOMETER	SOURCE	DETAILS
2016 Aug 30	114,315 KM	OpenRoad Lexus Port Moody, British Columbia, Canada	**Vehicle serviced** • Safety inspection performed • Tire repaired

Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact HONDA or visit **Honda's website.**

Stolen Vehicle Check

This vehicle is not actively declared stolen.

Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2007 Dec 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2008 Dec 20		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2009 Apr 1		Insurance Records British Columbia, Canada	VANDALISM	
2009 Jun 20		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2009 Sep 19		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2010 Sep 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2011 Feb 8		Insurance Records British Columbia, Canada	COLLISION	RIGHT FRONT CORNER
2011 Feb 8		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a RIGHT FRONT CORNER
2011 Aug 27		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2011 Oct 4		Insurance Records British Columbia, Canada	COLLISION	RIGHT SIDE

5J6RE48758L805420

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2011 Oct 4		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a RIGHT SIDE
2012 Sep 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2013 Jul 6		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Aug 31		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2014 Aug 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Aug 29		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Aug 9	113,266 KM	Mobil 1 Lube King Oil Change Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2016 Aug 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Aug 30	114,315 KM	OpenRoad Lexus Port Moody, British Columbia, Canada	Service Record	Vehicle serviced
2016 Sep 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Nov 14		Insurance Records British Columbia, Canada	COLLISION	LEFT FRONT CORNER
2016 Nov 14		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a LEFT FRONT CORNER
2017 Apr 22		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Nov 4		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2018 Feb 24		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Jun 17		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Dec 22		Insurance Records British Columbia, Canada	COLLISION	
2018 Dec 22		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a COLLISION

5J6RE48758L805420

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Jan 13		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Apr 21		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Dec 15		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2022 Jun 23		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported

Questions? We're here to help.

Visit us at **support.carfax.ca**

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at http://apps.icbc.com/registration/vchr/Limitation.html.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. **Conditions of Use**

© Copyright 2005 - 2022 CARFAX Canada ULC. All rights reserved.

CARFAX

5J6RE48758L805420

CUSTOMER #: N/A

390081

INTERNAL

HARMONY HONDA

HARMONY HONDA
2550 ENTERPRISE WAY
KELOWNA, BC V1X 7X5

PAGE 1

2550 Enterprise Way Kelowna, BC V1X 7X5
Service Direct: (250) 860-6530
Email:service@harmonyhonda.com
GST: 101447027RT0001

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 193 ANDREA JOHNSON

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
BLUE	08	HONDA CR-V	5J6RE48758L805420		146216/146216	TU8285

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			08:00 07OCT22		0.00	CASH	08OCT22

R.O. OPENED	READY	OPTIONS:
13:48 05OCT22	07:46 08OCT22	STK:U8285 DLR:1108

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
A PERFORM USED CAR SAFETY INSPECTION			
SAFETY PERFORM USED CAR SAFETY INSPECTION			
1312 IUVH 1.50		225.00	225.00
GAS FUEL CHARGE		89.32	89.32
1 15400-RTA-003 2 OIL FILTER CARTRI	13.38	12.74	12.74
5 020HO 0W20 SYTH OIL	10.70	10.70	53.50
1 94109-14000 8 WASHER DRAIN 14MM	0.64	0.64	0.64
PARTS: 66.88 LABOR: 225.00 OTHER: 89.32 TOTAL LINE A:			381.20
146216 1.50 Fuel: 89.32			
**********			
B PERFORM HONDA RECALL			
RECALL PERFORM HONDA RECALL			
1312 IUVH 0.00		0.00	0.00
**********			
C** REPLACE EVAP PRESSURE SENSOR			
GEN GENERAL REPAIR			
1312 IUVH 1.50		232.50	232.50
1 37940-SNA-A01 2 SENSOR VENT PRESS	195.93	195.93	195.93
PARTS: 195.93 LABOR: 232.50 OTHER: 0.00 TOTAL LINE C:			428.43
146216 1.50			
**********			
D** REPLACE REAR PADS AND MACHINE ROTORS			
GEN GENERAL REPAIR			
1312 IUVH 1.20		186.00	186.00
1 HW2 HARDWARE KIT	5.79	5.79	5.79
1 CA66932 8 CONT/BRKE CLEANER	7.21	7.21	7.21
1 43022-TP6-A02 F PAD SET RR	113.80	113.80	113.80
PARTS: 126.80 LABOR: 186.00 OTHER: 0.00 TOTAL LINE D:			312.80
146216 1.20			
**********			
E** REPLACE A/C CONDENSER			
GEN GENERAL REPAIR			
1312 IUVH 4.80		744.00	744.00
1 7-3599 CONDENSER	378.40	378.40	378.40

☐ I Consent to receive commercial electronic messages including news, special offers, advertisements and other promotional information from **HARMONY HONDA**, including its Agents. I can unsubscribe or withdraw my consent at any time using the unsubscribe method provided in the communication, or by contacting **HARMONY HONDA** at **2550 Enterprise Way, Kelowna, BritishColumbia,V1X 7X5, Service@harmonyhonda.com**or **Tel# 250-860-6500.**

x_____
CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
TAX	
PLEASE PAY THIS AMOUNT	

PARTS & SERVICE HOURS: MONDAY - FRIDAY 7:30 AM - 5:30 PM SATURDAY 8:00 AM - 4:30 PM

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2CE - IMAGING

INTERNAL COPY

CUSTOMER #: N/A

390081

INTERNAL

HARMONY HONDA

HARMONY HONDA
2550 ENTERPRISE WAY
KELOWNA, BC V1X 7X5

PAGE 2

2550 Enterprise Way Kelowna, BC V1X 7X5
Service Direct: (250) 860-6530
Email:service@harmonyhonda.com
GST: 101447027RT0001

HOME: CONT:N/A
BUS: CELL: SERVICE ADVISOR: 193 ANDREA JOHNSON

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
BLUE	08	HONDA CR-V	5J6RE48758L805420		146216/146216	TU8285

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			08:00 07OCT22		0.00	CASH	08OCT22

R.O. OPENED	READY	OPTIONS:
13:48 05OCT22	07:46 08OCT22	STK:U8285 DLR:1108

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
2	HW2			HARDWARE KIT	5.75	5.75	11.50
1	R134A			R134A RECHARGE	50.40	50.40	50.40
1	80872-SN7-003	2	O	RING 1/5"	9.79	9.79	9.79
1	80873-ST7-000	2	O	-RING 8MM	10.02	10.02	10.02

PARTS: 460.11 LABOR: 744.00 OTHER: 0.00 TOTAL LINE E: 1204.11
146216 4.80

****

F** REPLACE BATTERY

	BATT			REPLACE BATTERY			
		1312	IUVH	0.20		31.00	31.00
	BATT			BATTERY RECYCLING FEE		5.00	5.00
1	31500-CCA-H500R	C		BATTERY51R500CCA	207.22	207.22	207.22

PARTS: 207.22 LABOR: 31.00 OTHER: 5.00 TOTAL LINE F: 243.22
146216 0.30

****

G** MAINTENANCE MINDER (2) CARS/4 CYL TRUCKS 109.88

	91HOZ205			MAINTENANCE MINDER (2) CARS/4 CYL TRUCKS 109.88			
		1312	IUVH	0.30		49.55	49.55
1	17220-RZA-000	F		ELEMENT ASSY AIR/	23.44	23.44	23.44
41	80292-SDA-407	2		ELEMENT FILTER	39.91	39.91	1636.31

PARTS: 1659.75 LABOR: 49.55 OTHER: 0.00 TOTAL LINE G: 1709.30
146216 0.30
CHANGE ENGINE AIR FILTER AND CABIN AIR FILTER, INSPECT DRIVE BELT FOR WEAR
CHANGE ENGINE AIR FILTER AND CABIN AIR FILTER, INSPECT DRIVE BELT FOR WEAR

****

H** REPLACE REAR BLADE AND FRONT INSERTS

	GEN			GENERAL REPAIR			
		1312	IUVH	0.00		0.00	0.00
1	76730-SFA-003	2		BLADE WSHLD WIPER	34.44	34.44	34.44
1	76632-SWA-J02	F		BLADE RUBBER	10.83	10.83	10.83
1	76622-STK-A02	A		BLADE RUBBER	11.46	11.46	11.46

☐ I Consent to receive commercial electronic messages including news, special offers, advertisements and other promotional information from **HARMONY HONDA**, including its Agents. I can unsubscribe or withdraw my consent at any time using the unsubscribe method provided in the communication, or by contacting **HARMONY HONDA** at **2550 Enterprise Way, Kelowna, BritishColumbia,V1X 7X5, Service@harmonyhonda.com**or **Tel# 250-860-6500.**

x_____
CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
TAX	
PLEASE PAY THIS AMOUNT	

PARTS & SERVICE HOURS: MONDAY - FRIDAY 7:30 AM - 5:30 PM SATURDAY 8:00 AM - 4:30 PM

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2CE - IMAGING

INTERNAL COPY

CUSTOMER #: N/A

390081

INTERNAL

HARMONY HONDA

HARMONY HONDA
2550 ENTERPRISE WAY
KELOWNA, BC V1X 7X5

PAGE 3

2550 Enterprise Way Kelowna, BC V1X 7X5
Service Direct: (250) 860-6530
Email:service@harmonyhonda.com
GST: 101447027RT0001

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 193 ANDREA JOHNSON

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
BLUE	08	HONDA CR-V	5J6RE48758L805420		146216/146216	TU8285

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			08:00 07OCT22		0.00	CASH	08OCT22

R.O. OPENED	READY	OPTIONS:
13:48 05OCT22	07:46 08OCT22	STK:U8285 DLR:1108

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
PARTS: 56.73 LABOR: 0.00 OTHER: 0.00 TOTAL LINE H:			56.73
**********			
I** DIAG DRIVERS SIDE WINDOW NOT GOING DOWN			
GEN GENERAL REPAIR			
1312 IUVH 0.90		139.50	139.50
PARTS: 0.00 LABOR: 139.50 OTHER: 0.00 TOTAL LINE I:			139.50
146216 0.90 installed missing bolt on regulator.			
**********			

COST/SALE/COMP TOT: 206474 447529 0

☐ I Consent to receive commercial electronic messages including news, special offers, advertisements and other promotional information from **HARMONY HONDA**, including its Agents. I can unsubscribe or withdraw my consent at any time using the unsubscribe method provided in the communication, or by contacting **HARMONY HONDA** at **2550 Enterprise Way, Kelowna, BritishColumbia,V1X 7X5, Service@harmonyhonda.com**or **Tel# 250-860-6500.**

x_____
CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOUR AMOUNT	1607.55
PARTS AMOUNT	2773.42
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	94.32
TOTAL CHARGES	4475.29
LESS INSURANCE	0.00
TAX	0.00
PLEASE PAY THIS AMOUNT	4475.29

PARTS & SERVICE HOURS: MONDAY - FRIDAY 7:30 AM - 5:30 PM SATURDAY 8:00 AM - 4:30 PM

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2CE - IMAGING

INTERNAL COPY

Honda Multi-Point Vehicle Inspection Checklist

HARMONY Honda

HONDA GENUINE PARTS & SERVICE

BOOK YOUR NEXT SERVICE APPOINTMENT ONLINE.

R/O Number: 390081
Customer Name: .
Odometer: 146216
Next Service Due: A / 0 ☑ B ☐ 9 ☐
Advisor: Julie Schaufert
Technician: Adam Kopeck

Not Applicable or Not Checked

Satisfactory | May require future attention | Requires immediate attention

Main Item A / 0 / B

Under Hood

Engine Oil	✓
Windshield Washer Fluid Level	✓
Coolant level	✓
Power Steering Fluid	✓
Brake Fluid Level	✓
Transmission Fluid Level	✓
External Drive Belts and Radiator Hoses	✓
Air/Cabin/Dust & Pollen Filter	✓

Safety

Battery Condition (Date of Mfr: _____)	✓
Genuine Floor Mats Installed	✓
Anchored properly & 1 mat only in driver footwell	✓

Tires

All Season Tires: 6/32 or more | 4/32 to 5/32 | 3/32 or less
Winter Tires: 9/32 or more | 6/32 to 8/32 | 5/32 or less

Tire Condition LF: Tread 90% /32nds Wear Pattern	✓
Tire Condition RF: Tread 90% /32nds Wear Pattern	✓
Tire Condition LR: Tread 95% /32nds Wear Pattern	✓
Tire Condition RR: Tread 95% /32nds Wear Pattern	✓

Recommended: Rotation ☐ Alignment ☐ Replacement ☐
Seasonal Tire Changeover Recommended ☐

Interior / Exterior

Headlights (High / Low beam)	✓
Taillights (Running / Brake)	✓
Turn Signals (Hazards)	✓
Horn	✓
Parking Brake	✓
Windshield Washer Operation / Wipers	✓
Windshield Condition	✓
Clutch Operation (if applicable)	✓
Interior Lights	✓

Under Vehicle

Brakes / Lines / Hoses / Parking Brake Cable	✓
Shock Absorber / Struts / Suspension	✓
Tie Rod Ends, Steering Gear Box, Boots	✓
Driveshaft Boots / Bands	✓
Exhaust System / Heat Shields	✓
Catalytic Converter	✓
Fuel Lines and Connections	✓

Please Indicate Areas of External Damage or Wear



Main Item B & Sub-Item 9

Brake Condition

Pad Measurement: 5mm or more | 3-4mm | 2mm or less

Left Front: _____mm 70% %	✓
Right Front: _____mm 70% %	✓
Left Rear: _____mm 100% %	✓
Right Rear: _____mm 100% %	✓
Front Rotors: _____mm ☐ Turn ☐ Replace	✓
Rear Rotors: _____mm ☐ Turn ☐ Replace	✓
Rear Drums: _____mm ☐ Turn ☐ Replace	✓

Brake Service

A) Brake Lines / Hoses	✓
B) Brake Line Connections	✓
C) Honda M-77 Brake Caliper Assembly Paste	✓
D) Caliper Pin Boots	✓
E) Piston Seal	✓
F) Caliper Pins	✓
G) Pad Return Springs	✓



Maintenance Light Reset ☑ Yes ☐ N/A
Any Outstanding Recalls / Product updates? ☐ Yes ☑ No

Comments:

Lowest Price Guarantee on Tires* | Lifetime Brake Pad Guarantee* | Lowest Price Guarantee on 0W-20 Oil Changes*

** Some conditions and restrictions apply. Ask your Honda Service Advisor for complete details.*